

Contacted bug in wells, we pulled wells while pouring chips down the hole see photos attached. Also talked with Josh during the decommissioning. The times that were reported maybe off due to the site and speed of pulling wells.

WATER SUPPLY WELL REPORT - Map with location identified must be attached and shall include an approximate scale and north arrow

MULT 145351

4/8/2026

Map of Hole



4/8/2026

Map of Hole

