

85/4w/3ba

STATE OF OREGON WATER WELL REPORT (as required by ORS 537.765)

AUG - 7 1992

WATER RESOURCES DEPT. (START CARD) # 41607

POLK 498

(1) OWNER: Name Rickreall Water District Address P.O. Box 44 City Rickreall State OR Zip 97371

(9) LOCATION OF WELL by legal description: County Polk Township 8S N or S, Range 4W E or W, WM. Section 3 NE NW Tax Lot Lot Block Subdivision Street Address of Well (or nearest address) unknown

(2) TYPE OF WORK: Reseal [X] Recondition [] Abandon [] New Well [] Deepen []

(3) DRILL METHOD: [X] Rotary Air [] Rotary Mud [] Cable [] Other []

(4) PROPOSED USE: [X] Community [] Industrial [X] Irrigation [] Domestic [] Thermal [] Injection [] Other []

(5) BORE HOLE CONSTRUCTION: Special Construction approval Yes No Depth of Completed Well ft. Explosives used [] [X] Type Amount

Table with columns: HOLE Diameter, SEAL Material, Amount sacks or pounds. Row 1: 18 0 20 cement 5 20 36. Row 2: bent 0 5 8.

How was seal placed: Method [] A [] B [X] C [] D [] E [] Other [] Backfill placed from ft. to ft. Material Gravel placed from ft. to ft. Size of gravel

(6) CASING/LINER: Table with columns: Diameter, From, To, Gauge, Steel, Plastic, Welded, Threaded. Rows for Casing and Liner.

(7) PERFORATIONS/SCREENS: [] Perforations Method [] Screens Type Material

Table for perforations with columns: From, To, Slot size, Number, Diameter, Tele/pipe size, Casing, Liner.

(8) WELL TESTS: Minimum testing time is 1 hour. [] Pump [] Bailer [] Air [] Flowing Artesian. Yield gal/min, Drawdown, Drill stem at, Time.

Temperature of water Depth Artesian Flow Found Was a water analysis done? [] Yes By whom Did any strata contain water not suitable for intended use? [] Too little [] Salty [] Muddy [] Odor [] Colored [] Other Depth of strata:

(10) STATIC WATER LEVEL: 20 ft. below land surface. Date 7-6-92 Artesian pressure lb. per square inch. Date

(11) WATER BEARING ZONES: Table with columns: From, To, Estimated Flow Rate, SWL.

(12) WELL LOG: Table with columns: Material, From, To, SWL. Includes text: used 18" washover tool to reseal top 20' of hole.

Date started 7-6-92 Completed 7-6-92

(unbonded) Water Well Constructor Certification: I certify that the work I performed on the construction, alteration, or abandonment of this well is in compliance with Oregon well construction standards. Signed [Signature] WWC Number 723 Date 7-15-92

(bonded) Water Well Constructor Certification: I accept responsibility for the construction, alteration, or abandonment work performed on this well during the construction dates reported above. Signed [Signature] WWC Number 723 Date 7-15-92

STACO

WELL SERVICES INC

RECEIVED

AUG - 7 1992

Water Resources Department
3850 Portland Rd. NE
Salem, Oregon 97310

WATER RESOURCES DEPT.
SALEM, OREGON

Attention: Juno Trump

RE: Late Start Card No. 41607

Dear Juno,

Please find enclosed start card # 41607. We did not send the start card in prior to the beginning of the job, as we were hired to clean out the well only, which does not require a start card. However, once we began the job, we discovered that the well needed a new seal, hence the start card. Please accept our apologies.

Sincerely,



Tracy Fitzke
Office Manager
Staco Well Services, Inc.