

RECEIVED

MAR 19 1996

STATE OF OREGON
WATER SUPPLY WELL REPORT
(as required by ORS 537.765)

POIK
50048

(START CARD) # 86246

Instructions for completing this report are on the last page of this form WATER RESOURCES DEPT.

(1) OWNER: Well Number 1
Name Randy Roth
Address 742 S.E. Birch
City Dallas State Oregon Zip 97339

(2) TYPE OF WORK
 New Well Deepening Alteration (repair/recondition) Abandonment

(3) DRILL METHOD:
 Rotary Air Rotary Mud Cable Auger
 Other

(4) PROPOSED USE:
 Domestic Community Industrial Irrigation
 Thermal Injection Livestock Other

(5) BORE HOLE CONSTRUCTION:
Special Construction approval Yes No Depth of Completed Well 76 ft.
Explosives used Yes No Type _____ Amount _____

HOLE		SEAL					
Diameter	From To	Material	From To	Sacks or pounds			
14"	0 6	concrete	0 1	3			
10"	6 18.5	bentonite	1 18.5	8			
6"	8.5 76						

How was seal placed: Method A B C D E
 Other _____
Backfill placed from _____ ft. to _____ ft. Material _____
Gravel placed from _____ ft. to _____ ft. Size of gravel _____

(6) CASING/LINER:

Diameter	From	To	Gauge	Steel	Plastic	Welded	Threaded
Casing: 6"	+1.5	18.5	.250	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Liner: None				<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Final location of shoe(s) 18.5'

(7) PERFORATIONS/SCREENS:

From	To	Slot size	Number	Diameter	Material	Tele/pipe size	Casing	Liner
None								

(8) WELL TESTS: Minimum testing time is 1 hour
 Pump Bailer Air Artesian
Yield gal/min 110-120 Drawdown 76 Drill stem at 76 Time 2 hr.

Temperature of water 52° Depth Artesian Flow Found _____
Was a water analysis done? Yes By whom _____
Did any strata contain water not suitable for intended use? Too little
 Salty Muddy Odor Colored Other _____
Depth of strata: _____

(9) LOCATION OF WELL by legal description:
County Polk Latitude _____ Longitude _____
Township 7 N or S Range 5 E or W W.M.
Section 17 NE 1/4 NE 1/4
Tax Lot 101 Lot _____ Block _____ Subdivision _____
Street Address of Well (or nearest address) Reiner Rd. Dallas, Oregon

(10) STATIC WATER LEVEL:
_____ ft. below land surface. Date 3/15/96
Artesian pressure < 1 lb. per square inch. Date _____

(11) WATER BEARING ZONES:
Depth at which water was first found 4'

From	To	Estimated Flow Rate	SWL
4	6	10	—
35	60	110-120 gpm	+1.5'

(12) WELL LOG:
Ground Elevation _____

Material	From	To	SWL
broken rock	0	2	—
Large boulder	2	4	—
broken rock (black)	4	6	—
Hard gray basalt	6	76	+1.5'

Dickerson Well Drilling Inc
pH # 623-2664

Date started 2/27/96 Completed 3/2/96
(unbonded) Water Well Constructor Certification:

I certify that the work I performed on the construction, alteration, or abandonment of this well is in compliance with Oregon water supply well construction standards. Materials used and information reported above are true to the best of my knowledge and belief.
WWC Number _____
Signed _____ Date _____

(bonded) Water Well Constructor Certification:
I accept responsibility for the construction, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon water supply well construction standards. This report is true to the best of my knowledge and belief.
WWC Number _____
Signed William A. Blair Date _____