SHER 50378

WELL I.D. # L _____

(1) LAND OWNER Well Number Name Shift Man (a. High School Address 65912 Address 65912 High School Loo p City Moro State P Zip (2) TYPE OF WORK New Well Deepening Alteration (repair/recondition) New Well Deepening Alteration (repair/recondition) (3) DRILL METHOD: Rotary Air Rotary Mud Cable Auger Other	Township Section Tax Lot 5200 Street Address of (10) STATIC WAT 40ft.	Latitude <u>Nor S Rang</u> <u>NE</u> 1/4 Lot <u>Blow</u> Well (or nearest address ER LEVEL: below land surface. <u>Ib. per</u> RING ZONES:	ckS	E or W. 1/4 Subdivision _ High Sc Date Date	wм. <u>h•o] Lo</u> og 27/1977
		•			
	(12) WELL LOG:				
How was seal placed: Method A B C D E	Gro	und Elevation			
Other Backfill placed from ft. to ft. Material	Mate	rial	From	To	SWL
Gravel placed from ft. to ft. Size of gravel					
(6) CASING/LINER:	Basalt		0	135	
Casing: <u>8</u> ¹¹					
(7) PERFORATIONS/SCREENS:					
Perforations Method					
Screens Type Material					
Slot Tele/pipe From To size Number Diameter size Casing Liner	· · · · · · · · · · · · · · · · · · ·				
(8) WELL TESTS: Minimum testing time is 1 hour	Date started	Com	pleted		
Pump Bailer Air Artesian					
Yield gal/min Drawdown Drill stem at Time	SOURCE OF	DATA/INFO			
1 hr.	Woder Right		5 610 G	- 705	7
	_walki_kiga		1116 9		
Temperature of water Depth Artesian Flow Found Was a water analysis done? Yes By whom Did any strata contain water not suitable for intended use? Too little Salty Muddy Odor Colored Other Depth of strata:	COMPILED B	Y: Josh Hai ater Section	ckett, O	WRD	

WELL INFORMATION REPORT 11/16/2000