DEC 2 9 1907 WATER SUPPLY WELL REPORTED RESOURCES LEFT. 1.D. # < 12661
(as required by ORS 537.765) Instructions for completing this report are of the Magerian (9) LOCATION OF WELL by legal description: Well Number Longitude E & W. WM. N or S Range W 1/4 Cityen Iton Freeun Block (2) TYPE OF WORK New Well Deepening Alteration (repair/recondition) Abandonment Street Address of Well (or nearest address) (3) DRILL METHOD: (10) STATIC WATER LEVEL: Auger Cable Rotary Air Rotary Mud 143 _ ft. below land surface. Other Artesian pressure lb. per square inch. (4) PROPOSED USE: (11) WATER BEARING ZONES: Community Industrial ▼ Irrigation Domestic Other ☐ Injection Livestock Thermal Depth at which water was first found (5) BORE HOLE CONSTRUCTION: Special Construction approval Yes No Depth of Completed Well Estimated Flow Rate **SWL** From Explosives used Yes No Type 143 **SEAL** HOLE 790 143 Sacks or pounds 143 20 Berdendo 0 138 CRMENT 20 201 (12) WELL LOG: Ground Elevation _]C From То **SWL** Material Material Backfill placed from _ ft. to ft. Size of gravel Gravel placed from 230 3 Z (6) CASING/LINER: 230 240 Threaded Plastic Welded Gauge Steel 240 280 8 280 29⊅ \boxtimes \mathbf{E} 250 *330* 380 330 380 460 460 143 70 5° Final location of shoe(s) 885 205 (7) PERFORATIONS/SCREENS: 896 885 Perforations Method 896 Material Screens Tele/pipe Slot Casing Liner Number Diameter From Completed (8) WELL TESTS: Minimum testing time is 1 hour Date started (unbonded) Water Well Constructor Certification: Flowing I certify that the work I performed on the construction, alteration, or abandonment 🛛 Air ☐ Artesian Bailer Pump of this well is in compliance with Oregon water supply well construction standards. Materials used and information reported above are true to the best of my knowledge Time Drawdown Yield gal/min and belief. 1500+ WWC Number Signed (bonded) Water Well Constructor Certification: Depth Artesian Flow Found I accept responsibility for the construction, alteration, or abandonment work Was a water analysis done? Yes By whom performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon water supply well construction standards. This report is true to the best of my knowledge and belief. Did any strata contain water not suitable for intended use? Salty Muddy Odor Colored Other Depth of strata: