STATE OF OREGON WATER SUPPLY WELL REPORT (as required by ORS 537.765)

UMATH 53594

WELL I.D.# 29353-

(START CARD) # 098376

Instructions for completing this report are on the last page of this form. (1) OWNER: (9) LOCATION OF WELL by legal description: County Umatilla Latitude N or S Range 29 Address Subdivision (2) TYPE OF WORK New Well Deepening Alteration (repair/recondition) Abandonment Street Address of Well (or nearest address) (3) DRILL METHOD: Rotary Air Rotary Mud Cable Auger Other ft. below land surface. (4) PROPOSED USE: 1b. per square inch. Artesian pressure Domestic Industrial (11) WATER BEARING ZONES: Community Irrigation Thermal Injection Livestock Other (5) BORE HOLE CONSTRUCTION: Depth at which water was first found Special Construction approval Yes Yo Depth of Completed Well 175 ft SWL Explosives used Yes Yes Type Estimated Flow Rate Amount 152 HOLE SEAL Diameter From Sacks or pounds 10 (12) WELL LOG: Method Ground Elevation bentonite SWL Backfill placed from Material From to ft. Sanc Gravel placed from Size of gravel (6) CASING/LINER: Gauge Steel Plastic Welded Threaded 1 Soapstone 125 Liner: Final location of shoe(s) (7) PERFORATIONS/SCREENS: Perforations Method RECEIVED Material Screens Slot Tele/pipe Diameter Casing Liner From Number OCT 2 0 1999 WATER RESOURCES DEPT SALEM, OREGON (8) WELLTESTS: Minimum testing time is 1 hour Completed (unbonded) Water Well Constructor Certification: Flowing I certify that the work I performed on the construction, alteration, or abandonment Pump Bailer Artesian of this well is in compliance with Oregon water supply well construction standards. Yield gal/min Time Materials used and information reported above are true to the best of my knowledge 1 hr. and belief. WWC Number Signed Temperature of water Depth Artesian Flow Found (bonded) Water Well Constructor Certification: I accept responsibility for the construction, alteration, or abandonment work performed on this well during the construction dates reported above. All work Was a water analysis done? Yes By whom Did any strata contain water not suitable for intended use? performed during this time is in compliance with Oregon water supply well construction standards. This report is true to the best of my knowledge and belie Salty Muddy Odor Colored Other Depth of strata: Signed