TATE OF OREGON WATER WELL REPORT



•	IN/	28=///c	_
START CARD) #_	32007		_

(as required by ORS 537.765) New Well #2 (9) LOCATION OF WELL by legal description: (1) OWNER: Well Number City of Hermiston Umatilla_Latitude__ Name 180 NE 2nd St. Address N or S. Range Township. Hermiston 97838 of SW State Section (2) TYPE OF WORK: Block Street Address of Well (or nearest address) Newport Park, New Well ☐ Deepen Recondition Abandon corner of 5th & Newport, Hermiston, OR 97838 (3) DRILL METHOD: ☐ Rotary Mud Rotary Air (10) STATIC WATER LEVEL: **Cable** reverse circulation rotary ___ ft. below land surface. (4) PROPOSED USE: Artesian pressure lb. per square inch. X Community Industrial ☐ Irrigation (11) WATER BEARING ZONES: ☐ Domestic Other Thermal X Injection (5) BORE HOLE CONSTRUCTION: Depth at which water was first found Special Construction approval XX Yes No. Depth of Completed Well 1206 ft. Explosives used Yes No Type___ From Estimated Flow Rate Individual zone SWL & Attached log is marked 'WB' HOLE Amount flow are indeterminate next to believed significant Diameter From To Material From sacks or pounds 24 145 +1152 146 sacks if not otherwise noted cement water bearing zones. 521 45 521 cement 100 sacks on formation log. 14.75 521 1206 (12) WELL LOG: Ground elevation approx 445 How was seal placed: Method A B ₩ c Other Material From Backfill placed from_ ft. to_ ft. Material ft. to_470 Gravel placed from 152 see attached log Size of gravel (6) CASING/LINER: Diameter From Gauge Steel Plastic Welded Threaded 24 +1XX Casing: 20 $\mathbf{X}\mathbf{X}$ $\mathbf{X}\mathbf{X}$ П CALEM O *except 45 Final location of shoe(s) (7) PERFORATIONS/SCREENS: ☐ Perforations Method Material 304SS Type Vshape wire X Screens Slot Tele/pipe Casing From To size Number Diameter Liner 190 200 130 20 PS 260 270 130 20 (8) WELL TESTS: Minimum testing time is 1 hour 8/13/91 7/15/92 Date started Completed Flowing ☐ Air (unbonded) Water Well Constructor Certification: X Pump ☐ Bailer Artesian I certify that the work I performed on the construction, alteration, or abandon-Yield gal/min Drawdown Drill stem at Time ment of this well is in compliance with Oregon well construction standards. Materials used and information reported above are true to best knowledge and belief. see attached plots 1 hr. wwc Number 806 Date 8/14/92 Signed (bonded) Water Well Constructor Certification: Temperature of Water 72°F Depth Artesian Flow Found I accept responsibility for the construction, alteration, or abandonment work per-

Was a water analysis done? X Yes By whom owner

Did any strata contain water not suitable for intended use? Salty Muddy Odor Colored Other

An Date


formed on this well during the construction dates reported above. All work performed

during this time is in compliance with fregon well construction standards. This report


WWC Number_

SWL

HERMISTON WELL NO. 32007 PUMP TEST 6/12/92 STEP 1:Q= 978 AVG GPM




HERMISTION WELL No. 32007 PUMP TEST 6/12/92 STEP 2:Q=1502 AVG GPM




ar(cived

HERMISTON WELL No. 32007 PUMP TEST 6/12/92 STEP 3:Q=1982 AVG GPM




MECEIVED

HERMISTON WELL No. 32007 PUMP TEST 6/12/92 STEP 4:Q=2374 AVG GPM




MELLIVED

HERMISTON WELL No. 32007 PUMP TEST 6/16-17/92 Q=1982 AVG GPM



allive)

HERMISTON WELL No. 32007 RECOVERY TEST 6/17-22/92 Q=1982 AVG GPM



MELTIVED

12/21/22 13/24/1922



WATER
RESOURCES
DEPARTMENT

07/23/92

Steve Schneider 21881 River Rd N.E. St. Paul, Oregon 97137 Watermaster

RE: Special Standards for Hermistons new well #2; SC#32007

Dear Steve,

SEP 1 0 1992

This is written conformation approving the special standards progranted to you by phone on July 10, 1992 by Brian Mayer LEM, OREGON

This standard is granted upon the condition that the well be completed as detailed in your letter dated July 07, 1992, a copy of which is attached.

Granting this special standard does not relieve the constructor and owner of the well from any future liability, in case the construction method provides an avenue for pollution the groundwater body.

Sincerly,

Michael Ladd

NC Regional Manager

cc: Dude Woodward - City of Hermiston



WELL DRILLING IRRIGATION CONTROL SYSTEMS



PUMPS ENGINEERED WATER SYSTEMS SALES AND SERVICE

FAX (503) 633-2668

21881 River Road N.E. St. Paul, Oregon 97137 (503) 633-2666

July 7, 1992

MELCIVED

SEP 1 0 1992

WATER RESUURCES DEPT. SALEM, OREGON

Water Resources Department North Central Region 3920 Westgate Pendleton, OR 97801 Attn: Brian Mayer

RE: City of Hermiston New Well No. 2; SC#32007

Dear Brian,

Pursuant to our phone conversation yesterday, this letter is our request for special standards on the above referenced well.

A formation log of the well is attached along with a sketch of the as-built to date. As you can see, a 24" diameter casing was driven as the upper borehole was drilled with cable tool to 45'. The casing was then cut at 34' on August 28, 1991, to aid in future removal during grouting. Subsequently, the rest of the well was constructed during which much vibration occurred along with substantial ground surface loading around the 24" casing. We have now been attempting to extract the 24" upper casing in order to simultaneously place a grout seal around the 20" casing. Our exhaustive efforts have failed even though we have utilized jacks exceeding a half million pounds of pull along with vibration from a down hole hammer. We have taxed/exceeded normal water well technology standards.

No additional water resource protection will be gained by extracting, or attempting to extract the 24" casing. The only alluvial water bearing within the depth of the 24" casing is that which is exposed to the surface and only extends to 15'. This shallow formation would not benefit from a standard 18' surface seal since it is directly connected to ground surface. Disturbing the 24" casing will only damage an otherwise very pronounced bond (seal) to the natural formation. We therefore

propose to leave the 24" casing in place and pump a cement grout seal full depth from the top of the pea gravel (150') to the surface, around the 20" casing. This will provide more than standard protection for the waters in the basalt. Will this meet with your approval?

Thank you for your prompt review of this abnormal situation.

Sincerely,

SEP 1 0 1992

WATER RESOURCES DEPT. SALEM, OREGON

Stephen J. Schneider VP-Drill Operations

SJS/kss L1022.COH

Stan Wallulis, Wallulis & Assoc. cc: Dude Woodward, City of Hermiston

-20" casing 241 casing ground surface to SEP 1 0 1992 -bottom of 24"casing & shoe Q45" SWL in annulus is 94! top of pea gravel @ 152 20" PS 55 screen 190'-200' -pen gravel 20" PS 55 5creen 260'-270' Estion of pregravel, top of grout 0470' -cement grout botom of 23" & borehole & grout @521' 143/4" popen hole

City of Hermiston New Well No. 2 by Schneider Drilling Co. S.C. #32007



From	To	Description SEP 1 0 1992
		VAIER RESOURCE
0	1	Top soil SALEM, OREGON
1	JE WB	Sand, coarse
9	"" ک <u>ا</u> 15	Boulders, gravel, & sand
15 25	25	Clay, greenish brown w/gravel imbedded
25	30 35	Clay, blue w/claystone, & some claystone brown
30	35 22	Claystone & clay, blue w/some rock pieces
35	38	CS, blue & clay, blue & basalt, blk, vesicular
38 40	40	Basalt, blk, vesicular, w/claystone, blue
43	43 46	Basalt, blk, vesicular, w/clay & claystone blue
46	4 0 65	Basalt, blk, vesicular, med
65	155	Basalt, blk, fractured, med
155	160	Basalt, blk w/some fractures, med-hard Basalt, blk, fractured w/claystone, hard, gray
160	165	Basalt, blk, cindery w/clay, blk
165	175	Sandstone, blk & clay, blk
175	(WD	Sandstone and pea gravel cemented w/clay, blk
185	185 \ 50gpm	Basalt, broken, blk w/clay, green
190	204	Basalt, blk, well fractured
204	228	Basalt, gray, hard w/some fractures
228	233]	Basalt, blk, fractured
233	235) WB	Basalt, & clay, green
235	246	Clay & claystone, green
246	250)	Basalt, blk, & claystone, green
250	260	Basalt, blk, vesicular, broken w/some clay
260	265 \ WB	Basalt, blk, cindery
265	270) 100gpm	Basalt, blk, broken & clay, green
270	279/	Basalt, red & blk, vesicular, cindery
279	288	Basalt, gray, fractured, hard
288 294	294	Basalt, gray w/some fractures, hard
303	303 318	Basalt, gray, well fractured, med-hard
318	325	Basalt, gray, w/some fractures, hard Basalt, gray, fractured, med-hard
325	373	Basalt, gray, w/some fractures, hard
373	384	Basalt, blk, fractured, med-hard
384	390	Basalt, blk, w/claystone green, soft
390	398	Basalt, blk, well fractured, vesicular
398	404	Basalt, blk, fractured, med
404	415	Basalt, blk w/some claystone, vesicular
415	420	Basalt, blk, fractured, med-hard
420	435	Basalt, blk, hard
435	439	Basalt, blk w/claystone, soft
439	455	Basalt, blk, fractured, med-hard
455	505	Basalt, gray w/some fractures, hard
505	520	Basalt, gray w/fractures, hard
520	525	Basalt, gray & blk, fractured, med-hard
525	528	Basalt, gray, very hard, fractured
528	553	Basalt, gray, hard

```
553
       555
                 Basalt, blk w/green claystone
       559
555
                 Basalt, blk vesicular
                                                           RECEIVED
559
       590
                 Basalt, blk
            WB
590
       592
                 Basalt, blk, vesicular
                                                            SEP 1 0 1992
592
       626
                 Basalt, blk, fractured
626
       646
                 Basalt, blk, soft
                                                        WATER RESOURCES DEP).
       666
646
                 Basalt, blk w/green claystone, soft
                                                           SALEM, OREGON
                 Basalt, blk w/green claystone
666
       670
670
       678
                 Basalt, gray w/green claystone
678
       690
                 Basalt, gray w/green claystone, hard
                 Basalt, blk, med-hard
690
      745
745
      760
                 Basalt, gray, med-hard
760
      762
                 Basalt, blk, med-hard
762
      785
                 Basalt, blk, med-hard, fractured
                 Basalt, gray, hard, fractured
785
      840
840
      847
                 Basalt, blk, soft, vesicular & fractured
847
      848
                 Basalt, blk, med, vesicular, fractured
848
                 Basalt, blk, med, fractured w/claystone
      852
852
      855
                 Basalt, brown & blk, med, vesicular
           • WB
855
      860
                 Basalt, blk, med, vesicular
860
      862
                 Basalt, blk, broken, med
862
      873
                 Basalt, blk, med-hard, fractured
873
      887
                 Basalt, blk & red, med-soft, fractured, vesicular
887
      901
                 Basalt, blk, med-hard, fractured w/claystone
901
      907
                 Basalt, blk, soft, vesicular, broken
907
      917
                 Basalt, blk, med-hard, fractured
917
      924
                 Basalt, gray, hard
924
      929
                 Basalt, blk, med-hard, fractured
929
      936
                 Basalt, gray, hard
936
      945
                 Basalt, blk, med, ves, broken, some med gray clay
945
      954
                 Basalt, blk, med-hard, vesicular
                 Basalt, gray, hard, fractured
954
      966
966
      967
                 Basalt, blk, hard, fractured
967
      979
                 Basalt, blk, med-hard, fractured
979
      987
                 Basalt, gray, hard
987
      992
                 Basalt, blk, med-hard, fractured
992
     1008
                 Basalt, gray, hard, fractured
1008 1015
                 Basalt, gray, hard w/brown streaks, fractured
1015 1052
                 Basalt, gray, fractured
1052 1056
                 Basalt, vesicular, blk
1056 1060(
                 Basalt, vesicular, multi-colored blk, brown, red
1060 1110
                 Basalt, gray, med-hard
1110 1145
                 Basalt, gray, med-hard, frac, very rough drilling
1145 1182- WB
                 Basalt, blk & gray, soft, vesicular
1182 1206
                 Basalt, blk & gray
```

'WB' means the so noted interval is believed to be a significant water bearing zone.

W32020