

DATA COLLECTION SHEET

WELL I.D. # L _____

(1) LAND OWNER Owner Well Number GP Well No. 1
 First Name Gabriel Last Name Pascuzzi
 Company _____
 Address 3400 SW Bertha Blvd
 City Portland State OR Zip _____

(2) TYPE OF WELL Water Well Monitoring Well Piezometer

(3) CURRENT OBSERVED USE
 Domestic Community Industrial Irrigation
 Thermal Injection Livestock Other _____

(4) BORE HOLE CONSTRUCTION Estimated Depth of Well >500 ft.

BORE HOLE			SEAL			
Diameter	From	To	Material	From	To	Sacks / Pounds

(5) CASING/LINER

Casing:	Diameter	From	To	Gauge	Steel	Plastic	Welded	Threaded
						<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Liner:					<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Drive Shoe used Inside Outside None
 Final location of shoe(s) _____

(6) PERFORATIONS/SCREENS

Perforations Screens Type _____ Material _____

From	To	Approx Slot Size	Number	Diameter	Tele/pipe size	Casing	Liner
						<input type="checkbox"/>	<input type="checkbox"/>
						<input type="checkbox"/>	<input type="checkbox"/>
						<input type="checkbox"/>	<input type="checkbox"/>

(7) WELL TESTS Date _____

Pump Bailer Air Flowing Artesian

Yield gal/min	Drawdown	Drill stem at	Time

Temperature of water _____
 Was a water analysis done? Yes By whom _____

(8) LOCATION OF WELL (legal description)
 County Washington County Map No _____
 Township 2 N 5 Range 2 E W WM Section 15
SW 1/4 of the NE 1/4 Tax Lot _____ Lot _____
 Lat _____ ° _____ ' _____ " or _____ DMS or DD
 Long _____ ° _____ ' _____ " or _____ DMS or DD
 Street Address of Well (or nearest address) 15th N & 27th W
for SE corner DLL 47

(9) STATIC WATER LEVEL
~50 ft. below land surface. Date 8/1/1963
 Artesian pressure _____ lb. per square inch Date _____

(10) WATER BEARING ZONES

From	To	Estimated Flow Rate	SWL

(11) LITHOLOGY Ground Elevation _____

Material	From	To
<u>Drilled in 1960 by Harty Brothers of Portland. Owner's claim is log was sent in but no log could be found on file. Driller could not find a copy of the log. Ended up drilling deeper than original plan (see 6). Total depth is unknown but apparently drilled "much further through hard rock" (as per letter from) owner dated 11/10/1961</u>		

Estimated date originally constructed between 7/25/1960 and 10/28/1960

SOURCE OF DATA / INFO USGS On-Site Observation
 Interview Other _____
Application File G-1430

COMPILED BY Halley Barnett, Groundwater
 DATE 9/4/2019