

New exempt use wells must be submitted with a map and recording fee.

6/9/2022

START CARD #

1056161

ORIGINAL LOG #

(2a) PRE-ALTERATION

[illegible]

(5) BORE HOLE CONSTRUCTION

BORE HOLE			SEAL			sacks/	
Dia	From	To	Material	From	To	Amt	lbs
					Calculated		
					Calculated		
					Calculated		
					Calculated		

FILTER PACK

From	To	Material	Size

(6) CASING/LINER

Casing Liner	Dia	+	From	To	Gauge	Stl	Plstc	Wld	Thrd
									
									
									
									
									
									
									
									
									
									

(7) PERFORATIONS/SCREENS

[illegible]

(8) WELL TESTS: Minimum testing time is 1 hour

Yield gal/min	Drawdown	Drill stem/Pump depth	Duration (hr)
---------------	----------	-----------------------	---------------

Water Quality Concerns

[illegible]

(10) STATIC WATER LEVEL

[illegible]

(11) WELL LOG

[illegible]

Comments/Remarks

perforated the 6" casing and tremie grouted - verified with Tommy Laird and received verbal approval to top boring with bentonite chips

WATER SUPPLY WELL REPORT - Map with location identified must be attached and shall include an approximate scale and north arrow

WASH 80461

6/9/2022

Map of Hole

STATE OF OREGON WELL LOCATION MAP

This map is supplemental to the WATER SUPPLY WELL REPORT

Oregon Water Resources Department

725 Summer St NE, Salem OR 97301
(503)986-0900



LOCATION OF WELL

Latitude: 45.49921195 Datum: WGS84

Longitude: -122.92658720

Township/Range/Section/Quarter-Quarter Section:

WM1.00S2.00W10SWNW

Address of Well:

24220 SW TUALATIN VALLEY HWY, HILLSBORO, OR 97123

Hole Nbr: WW-1

Printed: June 9, 2022

DISCLAIMER: This map is intended to represent the approximate location the well. It is not intended to be construed as survey accurate in any manner.

Provided by well constructor

