State of Oregon 50150		RECEIVE
WATER WELL REPORT (as required by ORS 537.765) (1) OWNER: Well No. 1594 Name ROBINSON NURSERY Address PO BOX 1258 City MCMINNVILLE St OR Zip 97128	(9) LOCATION OF WELL by legal description: County YAMHILL Lat. ' " Long. ' "WATE	JUN - 5 1996 ER RESOURCES DE SALEM, OREGON
(2) TYPE OF WORK: NEW WELL (3) DRILL METHOD: CABLE (4) PROPOSED USE: DOMESTIC	9339 SW TRESTLE VIEW MCMINNVILLE, OR (10) STATIC WATER LEVEL: 30 ft. below land surface. Date 05/31/96 Artesian pressure lb per square in. Date	
(5) BORE HOLE CONSTRUCTION: Special Construction Approval: NO Depth of Compl. Well 119 ft Explosives used NO Type Amount HOLE SEAL Diam. From To Material From To Amount 10 0 119 BENTONITE 0 35 29 SAX	(11) WATER BEARING ZONES: Depth at which water was first found 69 From To Est Flow Rate SWL 69 118 25 30	
Seal placement method POURED/TAMPED Backfill: from ft to ft Material Cravel: from 35 ft to 119 ft Size 3/8" PEA (6) CASING/LINER: Diam. From To Gauge Material Connection Casing 6 +1 119 .25 STEEL WELDED Liner Final Location of shoe(s) NO SHOE (7) PERFORATIONS/SCREENS: [X] Perforations Method TORCH [] Screens Type Material Slot Tele/pipe From To Size Number Diam. size Casing/liner 99 117 6" 72 CASING	Cound elevation Material From To SWL	
(8) WELL TESTS: Minimum testing time is 1 hour Test type BAILER Draw- Drill stem Yield GPM down at Time	Ounded) Water Well Constructor Certification: I certify that the work I performed on the construction, alteration, or abandonment of this well is in compliance with Oregon water supply well construction standards. Materials used and information reported above are true to my best knowledge and belief. Signed	
25 38 1 hr. 25 38 6 Temperature of water 53 Depth Artesian Flow Found Was water analysis done? NO By whom Reason for water not suitable for use Depth of strata 0	(bonded) Water Well Constructor Certification: I accept responsibility for the construction, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon water supply well construction standards. This report is true to the best of my knowledge and belief. Signed	