STATE OF OREGON WATER RESOURCES DEPARTMENT

REQUEST FOR WRITTEN APPROVAL TO USE CONSTRUCTION METHODS NOT INCLUDED IN THE RULES AND REGULATIONS PRESCRIBING GENERAL STANDARDS FOR THE CONSTRUCTION AND MAINTENANCE OF WELLS IN OREGON

Before approval can be considered the following questions must be answered. Requests shall be submitted to the Watermaster Division, 3850 Portland Road, NE, Salem, OR 97310. Well Constructor: 1/4 of Section SH . (1) Location of Well: Township $\angle 5$, Range I W. WAShington County. Address at well site or nearest known address: 11911 SW WALDO WAY Sherwood, (2) Name and address of Landowner: (3) The distance to the nearest well and septic drainfield: (4) The unusual conditions existing at the well site: (5) The proposed construction methods that the well constructor or landowner constructing the well believes will be adequate for his particular well:

(6) A diagram showing the pertinent features of the proposed well design and construction (attach additional sheet if necessary):

See AHAChed

For Water Resources Department Use Only

Date:

Approved by:

Denied by:

Remarks:

NOTE:

- (1) If approval, all other phases of construction must be in compliance with State Well Construction Standards.
- (2) If it should be determined at some future date that the well, due to its construction, is offering an avenue for pollution of the ground water body, it will be necessary for you to return to the site to correct any well deficiences.

. 1/07/95 10:40

☎503 375 0961

2003/003

WEIL BY THE ROCK CRUSHER WW #2

Scott Parker

Static was not TAKEN DUE TO LACK OF DAYLIGHT

3/4 MINUS BLEACHED -> 220	
	1. 2.
Now to water Part	12000
1/8 HOLE 4 BAGS BENT 227	
CEMENT BEACKS - 243'	
COMENT BUTTERS	/////
3/8 Hole. BENT 247'	
3/4 ROUND ROCK - 250'	
77 RUDING RUCK - 7 SEE S	3/4 ROCK

NEW BOHOM OF WETI AFTER BACKFILL liNER below CASING 1'

219' total lINER INSTALLED BoHom 60' perferation 30 perf-per zo' 60 tota

Static NOT TAKEN NEIL DEPTH 220'