

RECEIVED

JAN 30 1998

WATER RESOURCES DEPT.
SALEM, OREGON

STATE OF OREGON
WATER RESOURCES DEPARTMENT

REQUEST FOR WRITTEN APPROVAL TO USE CONSTRUCTION METHODS NOT
INCLUDED IN THE RULES AND REGULATIONS PRESCRIBING GENERAL STANDARDS
FOR THE CONSTRUCTION AND MAINTENANCE OF WELLS IN OREGON

Before approval can be considered the following questions must be answered.

Requests shall be submitted to the Watermaster Division, 3850 Portland Road,
NE, Salem, OR 97310.

Date: 1/29/98

AMERICAN WELL DRILLING

Well Constructor: Rodney C. Ertle

(1) Location of Well: SE 1/4 SE 1/4 of Section 34,
Township 1-S, Range 2-W, Wasco County.

Address at well site or nearest known address: 22525 Tileflat Rd.

(2) Name and address of Landowner: Columbia Empire Farm Inc.
31461 NE Bell Rd.
Sherwood, OR. 97140


(3) The distance to the nearest well and septic drainfield: 55

(4) The unusual conditions existing at the well site: This drainfield was
Identified after the well was drill

(5) The proposed construction methods that the well constructor or landowner
constructing the well believes will be adequate for his particular well:
The well has a seal that is 78' deep we feel that at
that depth of seal that would be appropriate.

W-DF

(6) A diagram showing the pertinent features of the proposed well design and construction (attach additional sheet if necessary):



(Signed) Rodney C. Ehl
(WELL CONSTRUCTOR)

For Water Resources Department Use Only

Date: 2-24-98

Approved by: [Signature]

Denied by: _____

Remarks: _____

NOTE:

- (1) If approval, all other phases of construction must be in compliance with State Well Construction Standards.
- (2) If it should be determined at some future date that the well, due to its construction, is offering an avenue for pollution of the ground water body, it will be necessary for you to return to the site to correct any well deficiencies.