



Red dot indicates drilled well location.

X indicates dug well, used mostly for house supply until supply runs low.

Red dot indicates drilled well for electric power  
X indicates dug well for house supply until supply runs low  
Med. and small amount of water  
\$ 4.60

Locate well and acreage of irrigated land on plat.

Scale: 1" = 1 Mile  
4" = 1 Mile

STATE OF OREGON

County of Multnomah } ss.

I, Peter Straiff, being first duly sworn, do hereby certify that I have read the foregoing Registration Statement and that all of the items therein contained are true to the best of my knowledge and belief.

Peter Straiff  
(Signature of Registrant)

Subscribed and sworn to before me this 10 day of March, 1958

My commission expires October 19, 1959 Ernest P. Stovall  
(Notary Public)

(SEAL)

**CERTIFICATE OF REGISTRATION**

STATE OF OREGON } ss.  
County of Marion

This is to certify that the foregoing Registration Statement was received in the office of the State Engineer on the 27 day of March, 1958, at 8:00 o'clock A. M. and has been duly recorded in said office in Book No. 6 of Registration Statements on page GR-1244

Witness my hand this 19 day of September, 1958

Lewis A. Stanley  
(State Engineer)

By \_\_\_\_\_ (Deputy)