



Note: we only irrigate outside perimeter of our 9.0 acres or the 4.0 outside Acres.

Locate well and acreage of irrigated land on plat.  
Scale: 2" = 1 Mile

STATE OF OREGON

County of \_\_\_\_\_ } ss.

We <sup>W. E. Love</sup> ~~John H. Marshburn Jr~~ being first duly sworn, do hereby certify that I have read the foregoing Registration Statement and that all of the items therein contained are true to the best of my knowledge and belief.

*John H. Marshburn Jr*  
President  
Tri-City Drive in  
July 1958  
James M. Gentry  
Notary Public

Subscribed and sworn to before me this 11 day of \_\_\_\_\_ 1958

My commission expires \_\_\_\_\_  
MY COMMISSION EXPIRES FEB. 5, 1960

(SEAL)

CERTIFICATE OF REGISTRATION

STATE OF OREGON

County of Marion } ss.

This is to certify that the foregoing Registration Statement was received in the office of the State Engineer on the 14 day of July, 1958, at 8:00 o'clock A. M. and has been duly recorded in said office in Book No. 9 of Registration Statements on page GR-2046

Witness my hand this 16<sup>th</sup> day of February, 1959

*Lewis A. Stanley*  
(State Engineer)

By \_\_\_\_\_ (Deputy)

\$1500