



Locate well and acreage of irrigated land on plat.

Scale:  $\frac{1}{4}$ " = 1 Mile

STATE OF OREGON

County of Jackson

} ss.

I, H. E. Conger, being first duly sworn, do hereby certify that I have read the foregoing Registration Statement and that all of the items therein contained are true to the best of my knowledge and belief.

*H. E. Conger*  
 (Signature of Registrant)

Subscribed and sworn to before me this 27th day of May, 1957.

My commission expires August 25, 1958.

*L. G. R. [unclear]*  
 (Notary Public)

(SEAL)

**CERTIFICATE OF REGISTRATION**

STATE OF OREGON

County of Marion

} ss.

This is to certify that the foregoing Registration Statement was received in the office of the State Engineer on the 29th day of May, 1957 at 8:00 o'clock A. M. and has been duly recorded in said office in Book No. 3 of Registration Statements on page GR-483 C.

Witness my hand this 24th day of July, 1957.

*Lewis A. Stanley*  
 (State Engineer)

By \_\_\_\_\_ (Deputy)