



Locate well and acreage of irrigated land on plat.
Scale: 2" = 1 Mile

STATE OF OREGON }
County of Lane } ss.

I, Louis V. Gowdey, being first duly sworn, do hereby certify that I have read the foregoing Registration Statement and that all of the items therein contained are true to the best of my knowledge and belief.

Louis V. Gowdey
(Signature of Registrant)

Subscribed and sworn to before me this 12 day of Feb, 1958.

My commission expires NOVARY PUBLIC FOR OREGON
My Commission Expires 29th Day 1958 Chman
(Notary Public)

(SEAL)

CERTIFICATE OF REGISTRATION

STATE OF OREGON }
County of Marion } ss.

This is to certify that the foregoing Registration Statement was received in the office of the State Engineer on the 2 day of December, 1957, at 8:00 o'clock A.M. and has been duly recorded in said office in Book No. 5 of Registration Statements on page 812.

Witness my hand this 21 day of February, 1958.
Lewis A. Stanley
(State Engineer)

By _____
(Deputy)