



See Map in folder

Locate well and acreage of irrigated land on plat.

Scale: 2" = 1 Mile

STATE OF OREGON

County of Linn } ss.

I, Lloyd J. Porter, being first duly sworn, do hereby certify that I have read the foregoing Registration Statement and that all of the items therein contained are true to the best of my knowledge and belief.

Lloyd J. Porter
(Signature of Registrant)

Subscribed and sworn to before me this 11th day of March, 1958.

My commission expires MY COMMISSION EXPIRES DEC. 4, 1958

[Signature]
(Notary Public)

(SEAL)

CERTIFICATE OF REGISTRATION

STATE OF OREGON

County of Marion } ss.

This is to certify that the foregoing Registration Statement was received in the office of the State Engineer on the 10th day of March, 1958, at 10 o'clock A.M. and has been duly recorded in said office in Book No. 5 of Registration Statements on page 878.

Witness my hand this 24 day of April, 1958.

Lewis A. Dinkley
(State Engineer)

By _____ (Deputy)