

BEFORE THE STATE ENGINEER OF OREGON

LAKE COUNTY

IN THE MATTER OF THE ISSUANCE)
OF A CERTIFICATE CORRECTING)
AND SUPERSEDING WATER RIGHT)
CERTIFICATE NO. 11386, IN THE)
NAME OF THE ESTATE OF W. R.)
BERNARD.)

O R D E R


On January 30, 1936, Certificate No. 11386 was issued under Permit No. 11082, in the name of the Estate of W. R. Bernard, confirming a right to the use of water from waste and flood waters from Cottonwood Creek for the irrigation of 25.61 acres, among others, in Lot 2 (NW $\frac{1}{4}$ NW $\frac{1}{4}$), Section 13, Township 40 South, Range 19 East, W. M.

It was later discovered that Government Lot 2 is a portion of the SW $\frac{1}{4}$ NW $\frac{1}{4}$ of said section and that the NW $\frac{1}{4}$ NW $\frac{1}{4}$ is a complete forty-acre subdivision. Subsequent to this discovery, the certificate holder requested that the error be corrected.

It appears from the record that 25.61 acres were actually irrigated within the NW $\frac{1}{4}$ NW $\frac{1}{4}$ of said Section 13, that the error in description was due to an oversight, and that the rights of no other party will be injured by correcting such error.

IT IS THEREFORE ORDERED that Certificate No. 11578 be issued correcting and superseding Certificate No. 11386, so as to read 25.61 acres in the NW $\frac{1}{4}$ NW $\frac{1}{4}$ instead of 25.61 acres in Lot 2 (NW $\frac{1}{4}$ NW $\frac{1}{4}$), Section 13, Township 40 South, Range 19 East, W. M.

Dated at Salem, Oregon, this 9th day of September, 1936.


CHAS. E. STRICKLIN,
State Engineer.

LN