

RECEIVED

AUG 28 1997

P.O.T. FOUR CONC

RECEIVED

WATER RESOURCES DEPT. SALEM OREGON

SEP 19 1997

WATER RESOURCES DEPT. SALEM, OREGON

BOUNDARY SURVEY NOTE

THIS PARTITION PLAT WAS PREVIOUSLY BOUNDARY SURVEYED AND RECORDED AS C.S. 1087 ON APRIL 30, 1990 BY J.D. AND TWILA FLEGEL.

15 16 4
PNENE



SCALE 1" = 100'

NOTE
THERE IS NO NATIONAL GEODETIC CONTROL MONUMENT WITHIN ONE-HALF MILE OF THIS PROJECT.

SURVEY NARRATIVE
SURVEY NARRATIVE DETAILING HOW BOUNDARY LINES WERE ESTABLISHED IS CONTAINED ON SEPARATE SHEETS C 3 J WHICH ARE HEREBY MADE A PART OF THIS PARTITION PLAT.

LEGEND

- C J DEED RECORD B. 71 P. 501
- x - EXISTING FENCE LINE.
- * DENOTES IRON ROD RE-SET AT ORIGINAL LOCATION ON DEC. 27, 1990.

LEGEND

- SET 5/8" X 30" LONG IRON ROD WITH YELLOW CAP MARKED "ARMSTRONG - LS 1026". SEE
- FOUND 5/8" SMOOTH IRON ROD WITH 1-1/2", PER OREGON STATE HIGHWAY DEPARTMENT "PRINEVILLE-OCHOCCO DAM SECTION ~ OCHOCCO CROOK COUNTY, DRG. NO. 48-26-10 DATED REVISED SEPT., 1975".
- FOUND 2-1/2" O.D. X 30" GALV. IRON PIPE WITH 2 CAP AS PER CROOK COUNTY SURVEYOR C.R.L.C. RECORDED JAN. 18, 1988.
- FOUND 2-1/2" O.D. X 30" LONG ALUM. PIPE WITH CAP AS PER CROOK COUNTY SURVEYOR C.R.L.C. RECORDED FEB. 12, 1990.
- SET WITNESS CORNER, A 2-1/2" O.D. X 30" LONG WITH 2-1/2" ALUM. CAP AS PER CROOK COUNTY C.R.L.C.M. FORM RECORDED CONCURRENTLY IN OCHOCCO CREEK AND IS LOST; ESTABLISH BY THIS SURVEY. SEE C.S. 1087.

RECORDATION - CLERK

97867

STATE OF OREGON COUNTY OF CROOK

I CERTIFY THAT THE WITHIN INSTRUMENT WAS RECEIVED FOR RECORD ON THE 22 DAY OF December 1990 AT 1:50 P.M. AND RECORDED IN Partitions 97867

RECORDS OF SAID COUNTY MF NO DELLA M HARRISON, CROOK COUNTY CLERK

Della M. Harrison

55 54 N 89° 41' 22" W 114 54 N.E.
58 59 2612.27 59

C.R.L.C.M. O.I.D. ~ N 89° 43' W ~ 2614.0 589
1-18-1988 C.S. 40 ~ 589° 47' E ~ 2626 589
C.S. 1021 ~ 589° 37' 31" E ~ 2612.06 589
BACHAND ~ 1968 ~ C.S. 242 ~ 589° 49' W ~ 2613.90 589