Approved: March

## Мемо

To:	Kristopher Byrd, Well Construction Manager
From:	Tommy Laird, Well Construction Program Coordinator
Subject:	Review of Water Right Application G-19402
Date:	March 10, 2025

The attached application was forwarded to the Well Construction Section by the Groundwater Section. Gabriela Ferreira reviewed the application. Please see Gabriela's Groundwater Review and the Well Report.

Applicant's Well #Well 1 (Proposed): Well 1 is a proposed well, therefore it cannot be reviewed for construction. Construction of this proposed well shall be completed in a manner that protects ground water resources as required under Oregon Administrative Rules 690-200 through 690-240. During construction of this well, specific attention should be paid to ensure sealing requirements are met and that the well does not commingle aquifers.

The construction of proposed Well 1 may not satisfy hydraulic connection issues.

Applicant's Well #Well 2 (CLAC 12433): Based on a review of the Well Report, Well 2 does not appear to comply with current minimum well construction standards (See OAR 690 Division 210). The problem is that according to the Water Supply Well Report, the well head is flush with land surface. In order to meet minimum construction standards, the well head must be extended so that it is at least one foot above land surface.

My recommendation is that the Department not issue a permit for Well 2 unless it is brought into compliance with current minimum well construction standards or information is provided showing that it is constructed to meet current minimum well construction standards.

The repair of Well 2 may not satisfy hydraulic connection issues.

	RECEIVED	(1)
WATER WELL REPORT	APR 16 1981 State Well No	5/1E-23ba
STATE OF OREGON CLAC		1
/ULAU 012432	WATER RESOURCES DERTPermit No.	***************
	SALEM. OREGON	
(1) OWNER:	(10) LOCATION OF WELL:	
	01 0 0 0 0 0 0 0 0 0	<sub>number</sub> 3-15-81
Address 10227 MACKSBURG ROAD	County CLACKAMAS Driller's well NE 1/4 NW 1/4 Section 23 T. 4S	R. 1E W.M.
Address 10227 MACKSDONG NOAD City CANBY State OREGON	$\frac{1}{\text{Tax Lot #}} \frac{1}{00700} \frac{1}{\text{Lot}} = 1000$	Subdivision
97013	Address at well location: Same	
(2) TYPE OF WORK (check):	·	· .
New Well X Deepening  Reconditioning  Abandon If abandonment, describe material and procedure in Item 12.	(11) WATER LEVEL: Completed w	
	Depth at which water was first found	<u>    11     ft.</u>
(3) TYPE OF WELL: (4) PROPOSED USE (check):		and surface. Date 4-3-81
Rotary Air     Driven     D       Potary Mud     Dug     D       Irrigation     M       Test Well     Other	Artesian pressure Ibs. pe	r square inch. Date
A Bored  Thermal: Withdrawal Reinjection	(12) WELLLOG: Diameter of well below	casing8
(5) CASING INSTALLED: Steel A Plastic	Depth drilled 193 ft. Depth of	completed well 193 ft.
Threaded $\Box$ Welded $\lambda$	Formation: Describe color, texture, grain size and stru- thickness and nature of each stratum and aquifer pene	
8" Diam. from0ft. to16.3ft. Gauge	for each change of formation. Report each change in p	
"Diam. from	and indicate principal water-bearing strata.	
UINER INSTALLED:	MATERIAL	From To SWL
	TOP_SOIL	0 2
(6) PERFORATIONS: Perforated? Yes D No	CLAY BROWN	2 29
Type of perforator used Cutting torch	GRAVEL SAND BROWN	29 52
Size of perforations <sup>1</sup> / <sub>4</sub> in. by 8 in.	CLAY BROWN SAND FINE	<u>52 67</u> 67 87
60 perforations from 170 ft. to 186 ft.	GRAVEL SAND BROWN	67 87 87 106
perforations from ft. to ft.	CLAY BROWN SAND FINE	106 112
perforations from ft. to ft.	CLAY BLUE SAND BLACK	112 122
(7) SCREENS: Well screen installed?  Yes No	CLAY GRAY SAND BLACK FINE	122 133
Manufacturer's Name	SAND BLACK FINE	133 150
Type	CLAY GRAY SAND BLACK FINE	150 163
Diam. Slot Size	CLAY BLUE SAND BLACK	163 171
Diam	SANDSTONE BLACK	171 186 55
(8) WELL TESTS: Drawdown is amount water level is lowered below static level	CLAY GRAY	186 193
t: gal./min. with ft. drawdown after hrs.	·	
gal./min. with ft. drawdown after hrs.	· · · · · · · · · · · · · · · · · · ·	<b>├───</b>
Air test gal./min. with drill stem at ft. hrs.		· · · · · · · · · · · · · · · · · · ·
Bailer test 40 gal/min. with 20 ft. drawdown after 2 hrs.		
Amesian flow g.p.m.		
Depth artesian flow encountered ft.	0 10 01	ed 4-3 1981
(9) CONSTRUCTION: Special standards: Yes D No 🕅	Work started <u>3-18</u> 19 81 Complete Date well drilling machine moved off of well	4-3 19 81
Well seal—Material used	Drilling Machine Operator's Certification:	
Well sealed from land surface to		unervision Materials used
Diāmeter of well bore to bottom of seal 1.2 in.	This well was constructed under my directs and information reported above are true to the	est knowledge and belief.
Diameter of well bore below seal8in.	[Signed] XIII W. Banl M (Drilling Machine Operator)	Date
Number of sacks of cement used in well seal	Drilling Machine Operator's License No	)38
How was cement grout placed?pressure_grouted		
	Water Well Contractor's Certification:	
	This well was drilled under my jurisdiction the best of my knowledge and belief.	and this report is true to
Was pump installed?	Name BARNET DRILLING 1	PUMPS
Was a drive shoe used?       □XYes       □ No       Plugs       Plugs       Size: location	(Person, firm or corporation)	(Type or print)
2 No way business without the march of the start and the start of the	Address 101 26 CT 1203	SINCI VEL

NOTICE TO WATER WELL CONTRACTOR The original and first copy of this report are to be filed with the

7

WATER RESOURCES DEPARTMENT, SALEM, OREGON 97310 within 30 days from the date of well completion.

Contractor's License No. 764. Date 43

W

\$

...., 19..81

SP\*12658-690

0,

[Signed]