From: Michael Mattick

Sent: Thursday, January 27, 2011 2:58 PM

To: Kerry Kavanagh

Subject: FW: BOR contact and fish screen self cert

Hi K,

See the next message from me too.

MM

Michael J. Mattick
District 2 Watermaster
ph 541 682-3620
fax 541 746-1861
220 5th St, Springfield, OR 97477
generally open 8:30 am until 4:00 pm
Water Resources Department Web Page: www.wrd.state.or.us

From: Michael Mattick

Sent: Wednesday, January 19, 2011 11:14 AM

To: 'mw14@txstate.edu'

Subject: BOR contact and fish screen self cert

Hi Miles,

The BOR contact in Boise is Bill Parks, his email is: Parks Jr., William E [WParks@usbr.gov]

What I said to him in an email was:

I had a person named Miles Wilson fill out a Contract Data Sheet to use McKenzie River Storage to irrigate 0.1 acres. It turns out I did not need to make him do that, we can issue a permit for domestic use including .5 acres from the river and I will have him ask for a refund of his \$100, If that is possible.

The fish screen self certification form is at:

http://www.wrd.state.or.us/OWRD/PUBS/docs/forms/fish_screen.pdf

It will be included with the permit we send you.

You will most likely have a passive pump screen. I have tried to work out the calculations described in the form. Here is what I get:

The right will be for 0.01 cfs which is 4.5 gpm.

Minimum wetted screen area in square feet = 0.01 / 0.2 = 0.05 square feet X 144 (to get square inches) = 7.2 square inches of 1/16 inch screen if flat, or 3/32 inch screen if circular.

See You Later,

MM

Michael J. Mattick

1 of 2 1/28/2011 11:23 AM

District 2 Watermaster
ph 541 682-3620
fax 541 746-1861
220 5th St, Springfield, OR 97477
generally open 8:30 am until 4:00 pm
Water Resources Department Web Page: www.wrd.state.or.us

2 of 2 1/28/2011 11:23 AM