

- 1 (f) Type of well casing or liner material if any; and
2 (g) The proposed method of abandonment.
3 (2) A method to be used in the abandonment will be approved by the Department if the method
4 will adequately protect the ground water resource. Dug wells penetrating more than one water
5 bearing zone shall be abandoned in a manner to eliminate the possibility of leakage from one
6 water bearing zone to another.
7 (3) The well shall be abandoned by a licensed **W**[w]ater **S**[s]upply **W**[w]ell **C**[c]onstructor, a
8 landowner with a landowner well construction permit and bond, or by a landowner in the
9 presence of the watermaster or other Department representative.
10 Stat. Auth.: ORS 183, ORS 536, ORS 537 & ORS 540Stats. Implemented: ORS 183, ORS 536,
11 ORS 537 & ORS 540
12 Hist.: WRD 7-1988, f. & cert. ef. 6-29-88; WRD 7-2001, f. & cert. ef. 11-15-01
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41