


Harney Basin Synoptic Well Hydrographs

Harney Basin Groundwater Study
Advisory Committee Meeting
April 20, 2017




Darrick Boschmann, RG
Hydrogeologist
Oregon Water Resources Department

CROO 2936




CROO 53256




CROO 53258




CROO 53444




DESC 53516




DESC 55145




GRAN 800




HARN 9




HARN 198




HARN 219




HARN 243




HARN 296




HARN 323




HARN 440




HARN 441




HARN 463




HARN 503




HARN 547




HARN 607




HARN 637




HARN 657




HARN 696




HARN 722




HARN 751




HARN 754




HARN 755




HARN 782




HARN 812




HARN 813




HARN 991




HARN 994




HARN 1065




HARN 1085




HARN 1094




HARN 1245




HARN 1303




HARN 1309




HARN 1335




HARN 1363




HARN 1387




HARN 1393




HARN 1405




HARN 1408




HARN 1458




HARN 1459



HARN 1464




HARN 1467




HARN 1477




HARN 1482




HARN 1509




HARN 1510




HARN 1537




HARN 1540




HARN 1541




HARN 1548




HARN 1557




HARN 1562




HARN 1566




HARN 1603




HARN 1643




HARN 1656




HARN 1903




HARN 1981




HARN 1990




HARN 50151




HARN 50178




HARN 50179




HARN 50184




HARN 50233




HARN 50237




HARN 50301




HARN 50399




HARN 50407




HARN 50460




HARN 50474




HARN 50497




HARN 50514




HARN 50598




HARN 50612




HARN 50719




HARN 50734




HARN 50751




HARN 50766




HARN 50795




HARN 50950




HARN 50958




HARN 51004




HARN 51013




HARN 51014




HARN 51015




HARN 51017




HARN 51076



HARN 51086




HARN 51205




HARN 51233




HARN 51237




HARN 51238




HARN 51276



HARN 51327




HARN 51382




HARN 51445




HARN 51448



HARN 51475




HARN 51510




189


HARN 51524




HARN 51542




HARN 51547




HARN 51574




HARN 51584




HARN 51586




HARN 51611




HARN 51722




HARN 51734




HARN 51735




HARN 51736




HARN 51738




HARN 51756




HARN 51761




HARN 51767




HARN 51784




HARN 51830




HARN 51890




HARN 51921




HARN 51963




HARN 52021




HARN 52102




HARN 52111




HARN 52136




HARN 52234




HARN 52235




HARN 52494




HARN 52534




LAKE 1223



LAKE 1468



MALH 2322



Thank You

Questions?

Darrick E. Boschmann, RG | Hydrogeologist – Groundwater Section

Oregon Water Resources Department
725 Summer ST. NE., Suite A Salem OR 97301

| Phone: 503-986-0853
| Fax: 503-986-0902



Thank You

