		BAKE	53049	WELL I.D. LABEL# L	
WATER SUPPLY WELL	L REPORT		12025	START CARD #	1077030
	5 & 537.765 and OAR 690-205-0210)	3/31/	/2025	ORIGINAL LOG #	BAKER 52790
) LAND OWNER	Owner Well I.D.		_		
First Name RANDY	Last Name RUPP			ON OF WELL (legal d	
Company <u>RUPP RANCHES</u> Address 176 KRANICHWOOD S					S Range <u>39.00 E</u> E/W WM
City RICHLAND	State WA Zip 99352			E 1/4 of the	
) TYPE OF WORK		Conversion	0	" or 44.94637903	Lot DMS or DD
	on (complete 2a & 10) Abandonme	ent(complete 5a)	Lat°	or' or' or	30 DMS of DD DMS of DD
a) <b>PRE-ALTERATION</b> Dia + From	To Gauge Stl Plstc Wl	ld Thrd		et address of well ONea	
Casing: $6 \times 2$	78 0.250 • X			HAINES OR. 97833	
	From To Amt sacks/lbs				
Seal: Bentonite Chips	0 18 11 Sacks		(10) STATIC	WATER LEVEL	
) DRILL METHOD	Iud Cable Auger Cable M	Mud		Date	SWL(psi) + SWL(ft)
Reverse Rotary Othe		1 / Pre-Alteration 3/31/2025			
			Completed V	0,01,2020	D H 1 9
) PROPOSED USE	Domestic Irrigation Comm	nunity		Flowing Artesian?	Dry Hole?
Industrial/ Commericial X	Livestock Dewatering		WATER BEARIN		ter was first found
		<u> </u>	SWL Date	From To Est	Flow SWL(psi) + SWL(ft)
) BORE HOLE CONSTR	1	(Attach copy)			
Depth of Completed Well . BORE HOLE	n SEAL	sacks	/		
Dia From To	Material From To		/		
10 0 45	CEMENT 0 45	18 S	]		
	Calculate	ted	1		
	Calculate	ted	(11) WELL L	OG Ground Elevation	1 3332.95 FT
Seal placement method:	B C D E Other: POURED			Material	From To
	ft. to ft. Material		RESEALED WELI		0 45
Filter pack from ft. to		Size			
Explosives used: Type					
Seal Placement Begin Date 3/3	1/2025 Begin Time 00	00			
a) ABANDONMENT USI	ING UNHYDRATED BENT(	ONITE			
Proposed Amount	Actual Amount				
	Mat.	Shoe			
Proposed Amount	Mat.	Shoe Location			
Proposed Amount () CASING/LINER	Mat.	Shoe Location			
Proposed Amount () CASING/LINER	Mat.	Shoe Location			
Proposed Amount () CASING/LINER	Mat.	Shoe Location			
Proposed Amount () CASING/LINER	Mat.	Shoe Location			
Proposed Amount  CASING/LINER  C/L Dia + From	Mat. To Gauge Type Wld Thrd	Shoe Location			
Proposed Amount  C/L Dia + From  C/L Dia + From  Temp casing Yes Dia	Mat.       To     Gauge       Type     Wld       Thrd       Image: Strate s	Shoe Location			
Proposed Amount	Mat.         To       Gauge       Type       Wld       Thrd	Shoe Location			Image: Constraint of the sector of
Proposed Amount  CASING/LINER  C/L Dia + From  Temp casing Yes Dia  PERFORATIONS/SCRI Perforations Me Screens Type	Mat.       Mat.         To       Gauge       Type       Wld       Thrd         Image: Strate strat	Shoe Location	Construction Begin Date 3/31	/2025 Begin Time 00	00 End Date 3/31/2025
Proposed Amount  C/L Dia + From  C/L Dia + From  Temp casing Yes Dia  PERFORATIONS/SCRI  Perforations Me Screens Type Perf/ Casing/ Screen	Mat.         To       Gauge       Type       Wld       Thrd	Shoe         Location	Begin Date 3/31		00 End Date <u>3/31/2025</u>
Proposed Amount  C/L Dia + From  C/L Dia + From  Temp casing Yes Dia  PERFORATIONS/SCRI  Perforations Me  Screens Type Perf/ Casing/ Screen	Mat.         To       Gauge       Type       Wld       Thrd	Shoe Location	Begin Date <u>3/31</u> (unbonded) Wa	ter Well Constructor Certifie	cation
Proposed Amount  C/L Dia + From  C/L Dia + From  Temp casing Yes Dia  PERFORATIONS/SCRI  Perforations Me Screens Type Perf/ Casing/ Screen	Mat.         To       Gauge       Type       Wld       Thrd	Shoe         Location	Begin Date <u>3/31</u> ( <b>unbonded</b> ) Wa I certify that the abandonment of	ter Well Constructor Certific work I performed on the co this well is in compliance	<b>cation</b> nstruction, deepening, alteration, o e with Oregon water supply wel
Proposed Amount  C/L Dia + From  C/L Dia + From  Temp casing Yes Dia  PERFORATIONS/SCRI  Perforations Me Screens Type Perf/ Casing/ Screen	Mat.         To       Gauge       Type       Wld       Thrd	Shoe         Location	Begin Date <u>3/31</u> (unbonded) Wa I certify that the abandonment of construction star	ter Well Constructor Certific work I performed on the co this well is in compliance dards. Materials used and inf	<b>cation</b> nstruction, deepening, alteration, o
Proposed Amount  C/L Dia + From  C/L Dia + From  Temp casing Yes Dia  PERFORATIONS/SCRI  Perforations Me Screens Type Perf/ Casing/ Screen	Mat.         To       Gauge       Type       Wld       Thrd	Shoe         Location	Begin Date <u>3/31</u> (unbonded) Wa I certify that the abandonment of construction star the best of my kr	ter Well Constructor Certific work I performed on the co this well is in compliance dards. Materials used and introvided and belief.	cation nstruction, deepening, alteration, o with Oregon water supply wel formation reported above are true to
Proposed Amount  C/L Dia + From  C/L Dia + From  Temp casing Yes Dia  Perforations Me Screens Type Perf/ Casing/ Screen Screen Liner Dia Fro	Mat.         To       Gauge       Type       Wld       Thrd	Shoe         Location	Begin Date <u>3/31</u> (unbonded) Wa I certify that the abandonment of construction star the best of my kr	ter Well Constructor Certific work I performed on the co this well is in compliance dards. Materials used and info owledge and belief.	<b>cation</b> nstruction, deepening, alteration, o e with Oregon water supply wel
Proposed Amount  C/L Dia + From  C/L Dia + From  Temp casing Yes Dia  PERFORATIONS/SCRI  Perforations Me Screens Type Perf/ Casing/ Screen	Mat.         To       Gauge       Type       Wld       Thrd	Shoe Location	Begin Date <u>3/31</u> (unbonded) Wa I certify that the abandonment of construction star the best of my kr	ter Well Constructor Certific work I performed on the co this well is in compliance dards. Materials used and introvided and belief.	cation nstruction, deepening, alteration, o with Oregon water supply wel formation reported above are true to
Proposed Amount	Mat.         To       Gauge       Type       Wld       Thrd	Shoe Location	Begin Date <u>3/31</u> (unbonded) Wa I certify that the abandonment of construction star the best of my kr License Number Signed	ter Well Constructor Certific work I performed on the co this well is in compliance dards. Materials used and inf owledge and belief.	cation nstruction, deepening, alteration, o with Oregon water supply wel formation reported above are true to the
Proposed Amount	Mat.         To       Gauge       Type       Wld       Thrd	Shoe Location	Begin Date <u>3/31</u> (unbonded) Wa I certify that the abandonment of construction star the best of my kr License Number Signed (bonded) Water	ter Well Constructor Certific work I performed on the co this well is in compliance dards. Materials used and info owledge and belief. Da Well Constructor Certification	cation nstruction, deepening, alteration, o with Oregon water supply wel formation reported above are true to te te
Proposed Amount	Mat.         To       Gauge       Type       Wld       Thrd	Shoe Location	Begin Date <u>3/31</u> (unbonded) Wa I certify that the abandonment of construction star the best of my kr License Number Signed (bonded) Water I accept responsi	ter Well Constructor Certific work I performed on the co this well is in compliance dards. Materials used and introveledge and belief. Da Well Constructor Certification bility for the construction, de	cation nstruction, deepening, alteration, o with Oregon water supply wel formation reported above are true to te
Proposed Amount	Mat.         To       Gauge       Type       Wld       Thrd	Shoe Location	Begin Date <u>3/31</u> (unbonded) Wa I certify that the abandonment of construction star the best of my kr License Number Signed (bonded) Water I accept responsi work performed durin	ter Well Constructor Certific work I performed on the co this well is in compliance dards. Materials used and intro- owledge and belief. Da Well Constructor Certification bility for the construction, de on this well during the constru- g this time is in compliance	cation nstruction, deepening, alteration, o e with Oregon water supply wel formation reported above are true to te
Proposed Amount  C/L Dia + From  C/L Dia + From  Temp casing Yes Dia  Temp casing Yes Dia  PERFORATIONS/SCRI  Perforations Me  Screen Liner Dia Fro  Screen Liner Dia Fro  WELL TESTS: Minimun  Type of Test (g.	Mat.         To       Gauge       Type       Wld       Thrd	Shoe Location	Begin Date <u>3/31</u> (unbonded) Wa I certify that the abandonment of construction star the best of my kr License Number Signed (bonded) Water I accept responsi work performed durin	ter Well Constructor Certific work I performed on the co this well is in compliance dards. Materials used and intro- owledge and belief. Da Well Constructor Certification bility for the construction, de on this well during the constru- g this time is in compliance	cation nstruction, deepening, alteration, o e with Oregon water supply wel formation reported above are true to te
Proposed Amount	Mat. To Gauge Type Wld Thrd Gauge Type Wld Thrd Material To EENS ethod To Material To EENS ethod Material Material To To width length I I I I I I I I I I I I I I I I I I I	Shoe Location	Begin Date <u>3/31</u> (unbonded) Wa I certify that the abandonment of construction star the best of my kr License Number Signed (bonded) Water I accept responsi work performed durin construction stan	ter Well Constructor Certific work I performed on the co this well is in compliance dards. Materials used and info owledge and belief. Da Well Constructor Certificati bility for the construction, de on this well during the constru- g this time is in compliance dards. This report is true to the	cation nstruction, deepening, alteration, o e with Oregon water supply wel formation reported above are true to te
Proposed Amount	Mat.         To       Gauge       Type       Wld       Thrd	Shoe Location	Begin Date <u>3/31</u> (unbonded) Wa I certify that the abandonment of construction star the best of my kr License Number Signed (bonded) Water I accept responsi work performed durin construction stan License Number	ter Well Constructor Certific work I performed on the co this well is in compliance dards. Materials used and info iowledge and belief. 	cation nstruction, deepening, alteration, o e with Oregon water supply wel formation reported above are true to the

ORIGINAL - WATER RESOURCES DEPARTMENT THIS REPORT MUST BE SUBMITTED TO THE WATER RESOURCES DEPARTMENT WITHIN 30 DAYS OF COMPLETION OF WORK Form Version: New exempt use wells must be submitted with a map and recording fee.

WATER SUPPLY WELL REPORT - Map with location identified must be attached and shall include an approximate scale and north arrow **BAKE 53049** 

3/31/2025

Map of Hole

#### STATE OF OREGON WELL LOCATION MAP

This map is supplemental to the WATER SUPPLY WELL REPORT

### LOCATION OF WELL

Latitude: 44.94637903 Datum: WGS84 Longitude: -117.94568530 Township/Range/Section/Quarter-Quarter Section: WM7.00S39.00E21NENW Address of Well: 47347 HWY 30 HAINES OR. 97833

#### Oregon Water Resources Department 725 Summer St NE, Salem OR 97301



# Well Label: 138002

## Printed: March 31, 2025

DISCLAIMER: This map is intended to represent the approximate location the well. It is not intended to be construed as survey accurate in any manner.

Provided by well constructor

