

RECEIVED WITH WELL REPORT
NOV 13 1970 STATE OF OREGON
GON 97310 (Please type or print)
STATE ENGINEER
SALEM, OREGON
Do not write above this line

within 30 days from the date
of well completion.

State Permit No. _____

Name Harold Wray
Address PO Box 501

If abandonment, describe material and procedure in Item 12.

Rotary	☐	Driven	☐
Cable	☒	Jetted	☐
Dug	☐	Bored	☐

Domestic ☒ Industrial ☐ Municipal ☐
Irrigation ☐ Test Well ☐ Other ☐

6" Diam. from 0 ft. to 82 ft. Gage 250
 " Diam. from ft. to ft. Gage
 " Diam. from ft. to ft. Gage

Type of perforator used				CUTTING TOOL			
Size of perforations		in. by		in.			
62		perforations from 82		ft. to 54		ft.	
		perforations from		ft. to		ft.	
		perforations from		ft. to		ft.	

Manufacturer's Name

Type Model No.

Diam. Slot size Set from ft. to ft.

Diam. Slot size Set from ft. to ft.

Was a pump test made? ☐ Yes ☒ No If yes, by whom?			
Yield:	gal./min. with	ft. drawdown after	hrs.
"	"	"	"
	"	"	"

temperature of water Depth artesian flow encountered ft.

Well seal—Material used CEMENT DRILL MUD
Well sealed from land surface to 25 ft.
Diameter of well bore to bottom of seal 5 in.
Diameter of well bore below seal 6 in.
Number of sacks of cement used in well seal 2 sacks
Number of sacks of bentonite used in well seal _____ sacks
Brand name of bentonite _____
Number of pounds of bentonite per 100 gallons _____

Gravel placed from ft. to ft.

Bearing and distance from section or subdivision corner

Artesian pressure lbs. per square inch. Date

Formation: Describe color, texture, grain size and structure of materials; and show thickness and nature of each stratum and aquifer penetrated, with at least one entry for each change of formation. Report each change in position of Static Water Level and indicate principal water-bearing strata.

[illegible]

Date well drilling machine moved off of well 10-1 197

(Drilling Machine Operator)

Drilling Machine Operator's License No. 4187

(Water Well Contractor)

SP*45858-119