	AKE 52	11/25/2017	ORIGINAL LOG	#		
LAND OWNER Owner Well LD. irst Name MR. DENNIS Last Name FLYNN	<u> </u>				•	
ompany	(9) LOCATION OF WELL (legal description)					
ddress 31259 CLOVER FLAT ROAD	County LAKE Twp 35.00 S N/S Range 21.00 E E/W WM Sec 31 SE 1/4 of the NW 1/4 Tax Lot 2300					
ity LAKEVIEW State OR Zip 97630						
· ·	Conversion	Tax Map Number	" or <u>42.49445</u>	L	ot	DMS or DD
Alteration (complete 2a & 10) Abandonme	Lato	or <u>42.49445</u> " or <u>-120.291</u>	027		_ DMS or DD	
a) PRE-ALTERATION Dia + From To Gauge Stl Plstc Wld Th		LongStreet of	address of well \bullet	90012 Nearest add	race	_ DMS or DD
Casing: Dia + From To Gauge Stl Plstc Wld Th	\sim	LAT RD., LAKEVIEW		1035		
Material From To Amt sacks/lbs			, on 97030			
Seal:						
) DRILL METHOD		(10) STATIC W	VATER LEVEL			
Rotary Air Rotary Mud Cable Auger Cable M	Date SWL(psi) + SWL(ft) Existing Well / Pre-Alteration					
Reverse Rotary Other	Completed Wel					
PROPOSED USE Domestic X Irrigation Comm	unity		Flowing Artesian?		Hole?	
Industrial/ Commercial Livestock Dewatering	•	WATER BEARING	-	n water was f	irst found 2	27.00
Thermal Injection Other			-	Est Flow S		
					r(har)	
BORE HOLE CONSTRUCTION Special Standard Depth of Completed Well 622.00 ft.	(Attach copy)		27 110	50		27
BORE HOLE SEAL	sacks/	8/6/2015	<u>197 320</u>	400		21
	Amt lbs	8/18/2015	320 622	2000		21
22 0 150 Bentonite Chips 0 21	54 S] +				
18 150 344 Calculate						
12.25 344 622 Cement 21 340	203 S ed 199.28	(11) WELL LO	G		00	
How was seal placed: Method $A \square B \times C \square E$			Gibulia Eleva			
Other	, TE	Silty Clay and Sand	uterial v Loam		From 0	To 7
Backfill placed from ft. to ft. Material		Silty Sandy Brown Clay, Black Sand			7	110
Filter pack from ft. to ft. Material Size		Medium Red, Gray, Black & Yellow Tuft			110	145
		Brown Sandstone			145	197
			Some Brown Rock Mix	<u>x</u>	197	287
ABANDONMENT USING UNHYDRATED BENTC	INITE	Brown Sandstone Black Rock			287 320	320 345
Proposed Amount Actual Amount		Red Cinders			345	343
CASING/LINER	1, 11, 11, 17, 1	Red, Black and Broy	wn Cinders		375	390
$\begin{array}{c c c c c c c c c c c c c c c c c c c $		Black and Brown Po	orous Rock		390	622
$ \begin{array}{c c c c c c c c c c c c c c c c c c c $						
	XA H					
Shoe Inside Outside Other Location of shoe(s)					
Temp casing Yes Dia From + To						
PERFORATIONS/SCREENS						
Perforations Method		└────				
Screens Type Material	# of Tele/	Date Started 8/19/2015				
	(unbonded) Water Well Constructor Certification					
Screen Liner Dia From To width length	slots pipe size	` '	ork I performed on the		n, deepenin	g, alteration, o
		abandonment of th	his well is in complia	ance with (Oregon wat	er supply we
			rds. Materials used and	1 information	n reported a	bove are true t
		the best of my know	•	D-4		
		License Number		Date		
WELL TESTS: Minimum testing time is 1 hour		Signed				
	ng Artesian					
	on (hr)	· /	ell Constructor Certifi			
1000 280	2		ity for the construction			
			this well during the con- this time is in compli			
	I			ance with t	oregon wat	.c. suppry we
Temperature 79 °F Lab analysis Yes By		construction standar	ds. This report is true to	o the best of	my knowled	dge and belief.
Temperature 79 °F Lab analysis Yes By Water quality concerns? Yes (describe below) TDS amount 8: From Yes (describe below) TDS amount 8: Description	5 ppm	construction standar	ds. This report is true to		my knowled	
Water quality concerns? Yes (describe below) TDS amount 8:	5 ppm	construction standar License Number <u>13</u>	ds. This report is true to	to the best of Date $11/25$	my knowled	dge and belief.

ORIGINAL - WATER RESOURCES DEPARTMENT THIS REPORT MUST BE SUBMITTED TO THE WATER RESOURCES DEPARTMENT WITHIN 30 DAYS OF COMPLETION OF WORK Form Version:

WATER SUPPLY WELL REPORT - Map with location identified must be attached and shall include an approximate scale and north arrow LAKE 52807

11/25/2017

Map of Hole

STATE OF OREGON WELL LOCATION MAP

This map is supplemental to the WATER SUPPLY WELL REPORT

LOCATION OF WELL

Latitude: 42.4944502737 Datum: WGS84 Longitude: -120.29190011993 Township/Range/Section/Quarter-Quarter Section: WM 35S 21E 31 SENW Address of Well: 31259 CLOVER FLAT RD., LAKEVIEW, OR 97630

Oregon Water Resources Department

725 Summer St NE, Salem OR 97301 (503)986-0900



Well Label: 118390 Printed: November 6, 2017

DISCLAIMER: This map is intended to represent the approximate location the well. It is not intended to be construed as survey accurate in any manner.

Provided by well constructor

