

WEST 1/2 20°E

NE COR
SEC. 19

I, Glenn E Tyler of Lakeview Oregon do hereby certify that this map was made from notes taken during an actual survey made by me on August 22 1949, That the concrete Spring box shown hereon is S 21° 54' E, distance 214.90 from the NW Cor, S 1/2, N 1/2, NW 1/4, NE 1/4 Sec. 19- T36S- R21E W.M. which is a 3" Iron Pipe 30" long, And that the pipe line shown hereon is located on the ground as shown.

Glenn E Tyler
County Surveyor
Lake County Oregon



REGISTERED
COUNTY SURVEYOR
OCT 26 1949

REGISTERED
OREGON
LAND SURVEYOR
Glenn E Tyler
1949
GLENN E TYLER
250
24243

P: 19040
21399

MONUMENT

NW Cor. S 1/2, N 1/2
NW 1/4, NE 1/4 Sec. 19- T36S R21E W.M
3" Iron Pipe 30" Long

S 21° 54' E
214.9'

3' x 5' Concrete Spring Box

PASSAGE

N 88° 17' E
198'

Spring

PASSAGE

S 55° 53' E
127.10'

1 1/2" Pipe Line
S 56° 33' E

Corner

DRY CANYON

Flume

PASSAGE
1/2 ACRE
& GARDEN

Residence

Lily Pool

Residence

To Stock Water

Poultry & Stock Water

5 A± Irrigated Field

Culvert

PASSAGE

FREMONT

App. No. 24243

Per. No. 19040

MAP TO ACCOMPANY APPLICATION
of LYNDON PASSAGE
LAKEVIEW, OREGON
To appropriate waters from an
unnamed Spring and Creek, a tributary
to Crooked Creek, and located in
the NE 1/4 Sec. 19- T36S, R21E W. M. Oregon.

Scale 1" = 300'

36-21 ✓