



Chas. W. Shang Donation Land Claim

6" Drilled Well
 106' Deep with pump.
 The drilled well is situated in the
 North west corner of a dug well 5'x7'x40' deep,
 being extended 66' below bottom of dug
 well. The dug well has been used constantly
 for irrigation for more than 10 years.
 Due to recent dry years the water level has
 receded till it became necessary to drill
 66' deeper in the original dug well.

I, David G. Glass, of The Dalles, Oregon
 hereby certify that this map was made
 from notes taken in a survey made by me
 on May 14, 1931 and that it correctly
 shows the vicinity.

David G. Glass
 Professional Engineer
 Ore. No. 114

Sec 32, T. 2 N. R. 13 E.
 Scale 1" = 500
 Application No. U-56 Permit No. U. 51

N.W. Cor. Sec. 32

1/4 Cor. North Line Sec 32

N.E. Cor. Sec. 32

Lot 1

Lot 2

Lot 3

Lot 4

Lot 6

Lot 7

1/4 Cor.

32

1/4 corner
 (not found)

S.W. Cor Sec. 32 T. 2 N. R. 13 E. W.M.

S.W. Cor Sec. 32

West Line Sec. 32

E. line Sec. 32

2.88 ch
 27.48 ch

19.6 ch

26.12 ch

59.68 ch. by U.S. Field Notes

East 2751 ft.

556' W 1161.6'

1.6 AC
 2.81 AC

Catholic Mission D.L.C.