OWRD Water Resource Commission Meeting February 18th, 2021





2020 SW Region Hemp Audit Findings



Scott Prose – Assistant Watermaster, WRD



Jake Johnstone – Southwest Region Manager, WRD




Audit Defined

- Site Investigations
- Education
- Outreach
- Proactive
- Compliance& Enforcement
- Collaborative Effort



JW2

Registered Hemp locations in Southwest Oregon



+ 978 Hemp Sites □ County Boundary ■ ■ ■



This product is for informational purposes and may not have been prepared for, or be suitable for legal, engineering, or surveying purposes. Users of this information should review or consult the primary data and information sources to ascertain the usability of the information.



Replace map slides w/ maps w/ County borders JOHNSTONE Jake D * WRD, 1/19/2021 JW2



Site Visit Selection

With available registered* hemp grower data we:

*ODA Registered sites as of 9/11/2020


- 1. Identify greenhouses
- 2. Identify irrigation district sites
- 3. Address complaints
 - Registered or Unregistered
- 4. Ancillary Sites
- 5. Areas of heavy regulation/complaints
- 6. Compliance checks




Region Findings

*Data is from HGS registrations as of 9/11/2020 and OWRD input up to 10/31/2020

- The SW region had 978 Hemp Grower Registrations (HGS) 50% of state total
- We visited 187 registration sites which was 19.1% of the SW total
 - On site visits, 32.6% or
 61 of registrants were found to have violations.
 - Of those with violations 46 were using a well without a water right to do so



Inspections and Violations of Hemp Sites



187 Site Visits

County Roundary

*Of the 61 violations, 42 were ground water, 6 were curface water 1 had both and 0 other violations

have been prepared for, or be suitable for legal, engineering, or surveying purposes. Users of this information should review or consult the primary data and information sources to ascertain the usability of the information.





Findings cont.

- **34.4%** of violations (11.2% of total) lead to enforcement action
- 42.25% of visited sites claimed water truck deliveries as primary water source
- Approximately 75% of researched sites had valid water rights
- Of the 187 site visits, 27 had water rights and a violation



Findings cont.

- Of the 425 registered sites that had a WR research done, 320 had water rights of record
- Of the 187 site visits. 20 of those were initiated from a complaint
- Removing <u>complaint sites</u> from the audit totals drops the violation rate from 34.4% to 28.6%



Rogue Basin County Data

	Jackson	Josephine
Total ODA Registered Sites	530	358
Site Investigations	73	87
Percent of Sites with Investigations	14%	24%
Registered Sites With Violations	30	28
Water Right Researches Done	268	128
Claimed To Truck Water	33	41




2021-2022 Season

- Improve data QC
- Improve field data collection
- Address responsible party contact concerns
- Work to connect Watermasters with helpful data
- Support other Regions/Districts
- Continue to collaborate with ODA field inspectors


Questions & Discussion

-Additional Maps After this slide-


Southwest Hemp Violations




Williams Site Visits and Violations




Southwest Hemp Activity Overview



Water Rights Researched on Registrations



Water Rights Researched on Registrations



WR Research

+ All Hemp Sites



This product is for informational purposes and may not have been prepared for, or be suitable for legal, engineering, or surveying purposes. Users of this information should review or consult the primary data and information sources to ascertain the usability of the information.

