

#8

STATE OF OREGON
WATER WELL REPORT
(as required by ORS 537.765)

BAKE
2169

RECEIVED

AUG 18 1995

BS1438/60 AD

(START CARD) # W66021

Instructions for completing this report are on the last page of this form.

(1) OWNER:

Well Number 2

Name Broken Pike Mining Co. (Mike Dolan)
Address Rt 1 Box 13
City Huntington State OR Zip 97907

(2) TYPE OF WORK

☐ New Well ☒ Deepening ☒ Alteration (repair/recondition) ☐ Abandonment

(3) DRILL METHOD:

☐ Rotary Air ☐ Rotary Mud ☒ Cable ☐ Auger
☐ Other

(4) PROPOSED USE:

☐ Domestic ☐ Community ☐ Industrial ☐ Irrigation
☐ Thermal ☐ Injection ☐ Livestock ☒ Other Mining

(5) BORE HOLE CONSTRUCTION:

Special Construction approval ☐ Yes ☒ No Depth of Completed Well 350 ft.

Explosives used ☐ Yes ☒ No Type Amount

HOLE

SEAL

Diameter From To Material From To Sacks or pounds

8 195 350
EXISTING #2

How was seal placed: Method ☐ A ☐ B ☐ C ☐ D ☐ E

☐ Other

Backfill placed from ft. to ft. Material

Gravel placed from ft. to ft. Size of gravel

(6) CASING/LINER:

	Diameter	From	To	Gauge	Steel	Plastic	Welded	Threaded
Casing:	8"	+2	57	.250	☒	☐	☒	☐
	EXISTING				☐	☐	☐	☐
Liner:	#2	CASING			☐	☐	☐	☐

Final location of shoe(s)

(7) PERFORATIONS/SCREENS:

☐ Perforations Method
☐ Screens Type Material

From	To	Slot size	Number	Diameter	Tele/pipe size	Casing	Liner
						☐	☐
						☐	☐
						☐	☐
						☐	☐

(8) WELL TESTS: Minimum testing time is 1 hour

☐ Pump ☒ Bailer ☐ Air ☐ Flowing
Yield gal/min Drawdown Drill stem at Time

60 0 1 hr.

Temperature of water 48° Depth Artesian Flow Found

Was a water analysis done? ☐ Yes By whom

Did any strata contain water not suitable for intended use? ☐ Too little

☐ Salty ☐ Muddy ☐ Odor ☐ Colored ☐ Other

Depth of strata:

(9) LOCATION OF WELL by legal description:

County Baker Latitude Longitude
Township 13 N of S Range 43 E or W. WM.
Section 6 SE 1/4 NE 1/4
Tax Lot 500 Lot Block Subdivision
Street Address of Well (or nearest address)

Rye Valley, OR

(10) STATIC WATER LEVEL:

19 ft. below land surface. Date 3/8/95

Artesian pressure lb. per square inch. Date

(11) WATER BEARING ZONES:

Depth at which water was first found

From	To	Estimated Flow Rate	SWL
			19

(12) WELL LOG:

Ground Elevation

Material	From	To	SWL
Existing Depth	195		
Decomposed Granite	195	210	
Granite	210	242	
Brown Clay	242	249	
Granite	249	255	
Gray Clay	255	262	
Sandy Gray Clay	262	271	
Granite	271	280	
Gray Sandy Clay	280	283	
Granite	283	290	
Sandy Gray Clay	290	330	
Granite/Quartz	330	340	
Gray Clay (Cavey)	340	350	

Date started 3/5/95 Completed 3/8/95

(unbonded) Water Well Constructor Certification:

I certify that the work I performed on the construction, alteration, or abandonment of this well is in compliance with Oregon water supply well construction standards. Materials used and information reported above are true to the best of my knowledge and belief.

WWC Number

Signed Date

(bonded) Water Well Constructor Certification:

I accept responsibility for the construction, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon water supply well construction standards. This report is true to the best of my knowledge and belief.

WWC Number 1470

Signed Dennis Page Date 8/14/95