

BENT 55423

STATE OF OREGON WATER SUPPLY WELL REPORT

OCT 14 2016

(as required by ORS 537.765 & OAR 690-205-0210)

WELL I.D. LABEL# L 122819
START CARD # 1032401
ORIGINAL LOG #

(1) LAND OWNER Owner Well I.D. 5730 SALEM, OR
First Name Last Name
Company Stahlbush Island Farms
Address 3122 Stahlbush Island Rd.
City Corvallis State OR Zip 97333

(9) LOCATION OF WELL (legal description)
County BENTON Twp 11 S N/S Range 4 W E/W WM
Sec 8 NE 1/4 of the SW 1/4 Tax Lot 300
Tax Map Number Lot
Lat Long
Street address of well Nearest address
3400 NW Granger Ave. - Corvallis, OR 97330

(2) TYPE OF WORK [X] New Well [ ] Deepening [ ] Conversion
Alteration (complete 2a & 10) Abandonment (complete 5a)

(2a) PRE-ALTERATION
Dia + From To Gauge Stl Plstc Wld Thrld
Casing:
Material From To Amt sacks/lbs
Seal:

(3) DRILL METHOD
[X] Rotary Air [ ] Rotary Mud [ ] Cable [ ] Auger [ ] Cable Mud
[ ] Reverse Rotary [ ] Other

(4) PROPOSED USE [ ] Domestic [X] Irrigation [ ] Community
[ ] Industrial/ Commercial [ ] Livestock [ ] Dewatering
[ ] Thermal [ ] Injection [ ] Other

(5) BORE HOLE CONSTRUCTION Special Standard (Attach copy)
Depth of Completed Well 80 ft.
BORE HOLE SEAL sacks/lbs
Dia From To Material From To Amt S

How was seal placed: Method [ ] A [ ] B [X] C [ ] D [ ] E
Backfill placed from ft. to ft. Material
Filter pack from ft. to ft. Material Size
Explosives used: [ ] Yes Type Amount

(5a) ABANDONMENT USING UNHYDRATED BENTONITE
Proposed Amount Pounds Actual Amount Pounds

(6) CASING/LINER
Casing/Liner Dia + From To Gauge Stl Plstc Wld Thrld
Shoe [ ] Inside [ ] Outside [ ] Other Location of shoe(s)
Temp casing [ ] Yes Dia From To

(7) PERFORATIONS/SCREENS
Perforations Method Torch cut
Screens Type Material
Perf/S Casing/Screen Scrm/slot Slot # of Tele/
green Liner Dia From To width length slots pipe size

(8) WELL TESTS: Minimum testing time is 1 hour
[ ] Pump [ ] Bailer [ ] Air [ ] Flowing Artesian
Yield gal/min Drawdown Drill stem/Pump depth Duration (hr)
Temperature 55 °F Lab analysis [ ] Yes By
Water quality concerns? [ ] Yes (describe below) TDS amount 89
From To Description Amount Units

(10) STATIC WATER LEVEL
Date SWL(psi) + SWL(ft)
Existing Well / Pre-Alteration
Completed Well 09-30-2016 24
Flowing Artesian? Dry Hole?
WATER BEARING ZONES Depth water was first found 35
SWL Date From To Est Flow SWL(psi) + SWL(ft)

(11) WELL LOG Ground Elevation
Material From To
Brown clay 0 31
Brown sand 31 35
Sand & gravel 35 54
Blue clay 54 65
Brown sand 65 68
Blue clay 68 80
JONES DRILLING CO., INC.
29400 SANTIAM HWY.
LEBANON, OR 97355
541-367-2560 541-451-2686
1-800-915-8388

Date Started 09-27-2016 Completed 09-30-2016
(unbonded) Water Well Constructor Certification
I certify that the work I performed on the construction, deepening, alteration, or abandonment of this well is in compliance with Oregon water supply well construction standards. Materials used and information reported above are true to the best of my knowledge and belief.
License Number 1888 Date 10-11-2016
Signed
(bonded) Water Well Constructor Certification
I accept responsibility for the construction, deepening, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon water supply well construction standards. This report is true to the best of my knowledge and belief.
License Number 1684 Date 10-11-2016
Signed
Contact Info (optional) jonesdrilling@hotmail.com