

STATE OF OREGON
WATER SUPPLY WELL REPORT
(as required by ORS 537.765 & OAR 690-205-0210)

WELL I.D. LABEL# h/a
START CARD # 216121
ORIGINAL LOG # h/a

(1) LAND OWNER Owner Well I.D. BENT 56030
First Name Paula Last Name Pacheco
Company _____
Address 25383 Dawson Rd.
City Monroe State OR Zip 97456

(2) TYPE OF WORK ☐ New Well ☐ Deepening ☐ Conversion
☐ Alteration (complete 2a & 10) ☒ Abandonment (complete 5a)

(2a) PRE-ALTERATION
Dia + From To Gauge Stil Plstc Wld Thrd
Casing: ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐
Material From To Amt sacks/lbs
Seal: ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐

(3) DRILL METHOD
☐ Rotary Air ☐ Rotary Mud ☐ Cable ☐ Auger ☐ Cable Mud
☐ Reverse Rotary ☒ Other Poured by Hand

(4) PROPOSED USE ☐ Domestic ☐ Irrigation ☐ Community
☐ Industrial/ Commercial ☐ Livestock ☐ Dewatering
☐ Thermal ☐ Injection ☒ Other unknown

(5) BORE HOLE CONSTRUCTION Special Standard ☐ (Attach copy)
Depth of Completed Well 31' ft.

BORE HOLE SEAL
Dia From To Material From To Amt lbs
4" 0' 31' Bentonite 0' 31' 6 SCK
Calculated 6 SCK
Calculated

How was seal placed: Method ☐ A ☐ B ☐ C ☐ D ☐ E
☒ Other unknown
Backfill placed from _____ ft. to _____ ft. Material _____
Filter pack from _____ ft. to _____ ft. Material _____ Size _____
Explosives used: ☐ Yes Type _____ Amount _____

(5a) ABANDONMENT USING UNHYDRATED BENTONITE
Proposed Amount Pounds Actual Amount Pounds

(6) CASING/LINER
Casing Liner Dia + From To Gauge Stil Plstc Wld Thrd
☒ ☐ 4" ☐ unknown ☐ ☐ ☐ ☐ ☐
Shoe ☐ Inside ☐ Outside ☐ Other Location of shoe(s) unknown
Temp casing ☐ Yes Dia _____ From _____ To _____

(7) PERFORATIONS/SCREENS
Perforations Method unknown
Screens Type _____ Material _____
Perf/S Casing/ Screen Scrn/slot Slot # of Tele/
green Liner Dia From To width length slots pipe size

(8) WELL TESTS: Minimum testing time is 1 hour
☐ Pump ☐ Bailer ☐ Air ☐ Flowing Artesian

Yield gal/min Drawdown Drill stem/Pump depth Duration (hr)
Dry

Temperature Dry °F Lab analysis ☐ Yes By _____
Water quality concerns? ☐ Yes (describe below) TDS amount Dry
From To Description Amount Units

(9) LOCATION OF WELL (legal description)
County Benton Twp 14S N 6E Range 06W E/W WM
Sec 12 SE 1/4 of the SE 1/4 Tax Lot 800
Tax Map Number _____ Lot _____
Lat _____ " or _____ DMS or DD
Long _____ " or _____ DMS or DD
☒ Street address of well ☐ Nearest address

25383 Dawson Rd. Monroe, Or.

(10) STATIC WATER LEVEL
Date SWL(psi) + SWL(ft)
Existing Well / Pre-Alteration _____
Completed Well 10-7-19 Dry
Flowing Artesian? ☐ Dry Hole? ☐

WATER BEARING ZONES Depth water was first found Dry
SWL Date From To Est Flow SWL(psi) + SWL(ft)
10-7-19 0' 31' Dry Dry

(11) WELL LOG Ground Elevation _____
Material From To
Clay overburden
From 0' to 11'
Turning to Grey
Sand stone normal
For this well size
Permanent Abandonment
Special Standards approval

Date Started 10-7-19 Completed 10-7-19

(unbonded) Water Well Constructor Certification
I certify that the work I performed on the construction, deepening, alteration, or abandonment of this well is in compliance with Oregon water supply well construction standards. Materials used and information reported above are true to the best of my knowledge and belief.

License Number _____ Date _____
Signed _____

(bonded) Water Well Constructor Certification
I accept responsibility for the construction, deepening, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon water supply well construction standards. This report is true to the best of my knowledge and belief.

License Number 751 Date 10-7-19
Signed D. Joe Joving
Contact info (optional) Mid Valley Drilling Inc.