

STATE OF OREGON
WATER SUPPLY WELL REPORT
(as required by ORS 537.765 & OAR 690-205-0210)

WELL I.D. LABEL#	02240
START CARD #	216/20
ORIGINAL LOG #	Benton 50333

(1) LAND OWNER Owner Well I.D.
First Name Paula Last Name Pacheco
Company _____
Address 25383 Dawson Rd
City Phoenix State OR Zip 97456
(2) TYPE OF WORK ☐ New Well ☐ Deepening ☐ Conversion
Alteration (complete 2a & 10) ☒ Abandonment (complete 5a)

(2a) PRE-ALTERATION

	Dia	+	From	To	Gauge	Stl	Plstc	Wld	Thrd
Casing:	6"		1'	19'	250	☒	☐	☐	☐
	Material		From	To	Amt	sacks/lbs			
Seal:	Bentonite		0	19'	7	SCKS			

(3) DRILL METHOD
☐ Rotary Air ☐ Rotary Mud ☐ Cable ☐ Auger ☐ Cable Mud
☐ Reverse Rotary ☒ Other *Screened & Poured*

(4) PROPOSED USE ☒ Domestic ☐ Irrigation ☐ Community
☐ Industrial/ Commercial ☐ Livestock ☐ Dewatering
☐ Thermal ☐ Injection ☐ Other _____

(5) **BORE HOLE CONSTRUCTION** Special Standard ☐ (Attach copy)
Depth of Completed Well 190' ft.

BORE HOLE			SEAL			sacks/
Dia	From	To	Material	From	To	lbs
6"	+1'	190'	Bentonite	+1'	190'	58 sacks
					Calculated	54 sacks
					Calculated	

How was seal placed: Method ☐ A ☐ B ☐ C ☐ D ☐ E
☒ Other Screened & Poured
 Backfill placed from _____ ft. to _____ ft. Material _____
 Filter pack from _____ ft. to _____ ft. Material _____ Size _____
 Explosives used: ☐ Yes Type _____ Amount _____

(5a) ABANDONMENT USING UNHYDRATED BENTONITE
Proposed Amount 54 ~~54.3~~ Pounds Actual Amount 58 ~~58.5~~ Pounds

(6) CASING/LINER

Casing	Liner	Dia	+	From	To	Gauge	Stl	Plstc	Wld	Thrd
☒	☐	6"	☐	+1'	19'	250	☒	☐	☐	☐
☐	☐		☐	Undisturbed			☐	☐	☐	☐
☐	☐		☐				☐	☐	☐	☐
☐	☐		☐				☐	☐	☐	☐
☐	☐		☐				☐	☐	☐	☐

Shoe ☐ Inside ☐ Outside ☐ Other Location of shoe(s) None

Temp casing ☐ Yes Dia _____ From _____ To _____

[illegible]

(8) **WELL TESTS:** Minimum testing time is 1 hour

☐ Pump
 ☐ Bailer
 ☐ Air
 ☐ Flowing Artesian

Yield gal/min Drawdown Drill stem/Pump depth Duration (hr)

89 gpm	when orig. drilled		

Temperature 57 °F Lab analysis ☐ Yes By _____

Water quality concerns? ☐ Yes (describe below) TDS amount

From	To	Description	Amount	Units

BENT 56031

(9) LOCATION OF WELL (legal description)

County Benton Twp 14S N 0 Range 06W E 0 W

Sec 12 SE 1/4 of the SE 1/4 Tax Lot 800

Tax Map Number _____ Lot _____

Lat _____ " or _____ DMS or DD

Long _____ " or _____ DMS or DD

25383 Dawson Rd Monroeville OR

(10) STATIC WATER LEVEL			
	Date	SWL(psi)	+ SWL(ft)
Existing Well / Pre-Alteration			
Completed Well	10-7-19		62'
Flowing Artesian?	☐	Dry Hole?	☐

WATER BEARING ZONES			Depth water was first found	
SWL Date	From	To	Est Flow	SWL(psi) + SWL(ft)
8-22-96	121'	122'	89gpm	95'

[illegible]

Date Started 10-7-19 Completed 10-7-19

(unbonded) Water Well Constructor Certification
I certify that the work I performed on the construction, deepening, alteration, or abandonment of this well is in compliance with Oregon water supply well construction standards. Materials used and information reported above are true to the best of my knowledge and belief.

License Number _____ Date _____
Signed _____

(bonded) Water Well Constructor Certification
I accept responsibility for the construction, deepening, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon water supply well construction standards. This report is true to the best of my knowledge and belief.

License Number 751 Date 10-7-19
Signed D. Joe Loving
Contact Info (optional) Mid Valley Drilling Inc