Nb

STATE OF OREGON
WATER WELL REPORT
(as required by ORS 537.765)

Clac 17177

RECEIVED
DEC 13 1991
WATER RESOURCES DEPT.
SALEM, OREGON

3S/4E/29c

(START CARD) # 28784

(1) OWNER: Well Number:
Name Roger & Patricia Pharris
Address P. O. Box 1377
City Estacada State Or. Zip 97023

(2) TYPE OF WORK:
[X] New Well [ ] Deepen [ ] Recondition [ ] Abandon

(3) DRILL METHOD
[X] Rotary Air [ ] Rotary Mud [ ] Cable
[ ] Other

(4) PROPOSED USE:
[X] Domestic [ ] Community [ ] Industrial [ ] Irrigation
[ ] Thermal [ ] Injection [ ] Other

(5) BORE HOLE CONSTRUCTION:
Special Construction approval Yes [ ] No [X] Depth of Completed Well 118 ft.
Explosives used Yes [ ] No [X] Type Amount

HOLE Diameter	From	To	SEAL Material	From	To	Amount sacks or pounds
10"	0	20	P. Cem	0	20	5
8"	20	120				

How was seal placed: Method [ ] A [ ] B [X] C [ ] D [ ] E
[ ] Other
Backfill placed from 30 ft. to 118 ft. Material Pea Gravel
Gravel placed from ft. to ft. Size of gravel

(6) CASING/LINER:

	Diameter	From	To	Gauge	Steel	Plastic	Welded	Threaded
Casing:	6"	+1	118	200#	[ ]	[X]	[X]	[ ]
					[ ]	[ ]	[ ]	[ ]
					[ ]	[ ]	[ ]	[ ]
					[ ]	[ ]	[ ]	[ ]
Liner:					[ ]	[ ]	[ ]	[ ]
					[ ]	[ ]	[ ]	[ ]

Final location of shoe(s)

(7) PERFORATIONS/SCREENS:
[X] Perforations Method Circular saw
[ ] Screens Type Material

From	To	Slot size	Number	Diameter	Tele/pipe size	Casing	Liner
78	118	1/8 by 8"				[X]	[ ]
56 slots						[ ]	[ ]

(8) WELL TESTS: Minimum testing time is 1 hour
[X] Pump [ ] Bailer [ ] Air [ ] Flowing Artesian

Yield gal/min	Drawdown	Drill stem at	Time
			1 hr.
12gpm.	32-103	after 4 hrs	

Temperature of water 52 Depth Artesian Flow Found
Was a water analysis done? [ ] Yes By whom
Did any strata contain water not suitable for intended use? [ ] Too little
[ ] Salty [ ] Muddy [ ] Odor [ ] Colored [ ] Other
Depth of strata:

(9) LOCATION OF WELL by legal description:
County Clack Latitude ' " Longitude ' "
Township 3S N or S. Range 4E E or W. WM.
Section 29C ¼ ¼
Tax Lot 1300 Lot Block Subdivision
Street Address of Well (or nearest address) 27732 S. Hwy 211
Estacada, Oregon 97023

(10) STATIC WATER LEVEL:
32 ft. below land surface. Date 11-12-91
Artesian pressure lb. per square inch. Date

(11) WATER BEARING ZONES:
Depth at which water was first found 105

From	To	Estimated Flow Rate	SWL
105	120	12gpm	32

(12) WELL LOG: Ground elevation 600

Material	From	To	SWL
Top Soil	0	2	
Clay. red	2	15	
Clay, brown with bldrs med.	15	105	
Cemented gravel, loose	105	120	32

Date started 11-3-1991 Completed 11-12-1991

(unbonded) Water Well Constructor Certification:
I certify that the work I performed on the construction, alteration, or abandonment of this well is in compliance with Oregon well construction standards. Materials used and information reported above are true to my best knowledge and belief.
WWC Number
Signed Date

(bonded) Water Well Constructor Certification:
I accept responsibility for the construction, alteration, or abandonment work performed on this well during the construction dates reported above. all work performed during this time is in compliance with Oregon well construction standards. This report is true to the best of my knowledge and belief. Estacada WELL Drilling WWC Number 1459
Signed Ron Kelling Date 12-10-91

ORIGINAL & FIRST COPY - WATER RESOURCES DEPARTMENT SECOND COPY - CONSTRUCTOR THIRD COPY - CUSTOMER 9809C 3/88