

WATER RESOURCES DEPT.

Well Number

SALEM. (9) LOCATION OF WELL by legal description:

County Clack Latitude _____ Longitude _____
Township 3 N or S. Range 4 E or W. WM. ☒
Section 15C SE $\frac{1}{4}$ SW $\frac{1}{4}$
Tax Lot 1800 Lot _____ Block _____ Subdivision _____
Street Address of Well (or nearest address) 29790
SE Shogomick Lane - Estacada

☒ New Well ☐ Deepen ☐ Recondition ☐ Abandon

☐ Rotary Air ☐ Rotary Mud ☒ Cable
☐ Other

☒ Domestic ☐ Community ☐ Industrial ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other _____

Special Construction approval ☐ Yes ☒ No Depth of Completed Well 100 ft.
Explosives used ☐ Yes ☒ No Type _____ Amount _____

(10) STATIC WATER LEVEL:

26' ft. below land surface. Date 4-26-49
Artesian pressure _____ lb. per square inch. Date _____

(11) WATER BEARING ZONES:

Depth at which water was first found 45

From	To	Estimated Flow Rate	SWL
45	86	30	20

(12) WELL LOG:

Ground elevation

[illegible]

Date started 4-18-94 Completed 4-26-94

(unbonded) Water Well Constructor Certification:

I certify that the work I performed on the construction, alteration, or abandonment of this well is in compliance with Oregon well construction standards. Materials used and information reported above are true to my best knowledge and belief.

Signed Thomas Young WWC Number 1512
Date 4-26-97

(bonded) Water Well Constructor Certification:

I accept responsibility for the construction, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon well construction standards. This report is true to the best of my knowledge and belief.

Signed W.O. Youngberg WWC Number 237
Date 6-7-94

Final location of shoe(s)

(7) PERFORATIONS/SCREENS:

☐ Perforations Method _____
☒ Screens Type 10 ~~20~~ Material PVC

From	To	Slot size	Number	Diameter	Tel./pipe size	Casing	Liner
70	90	1/8"		4"	20'	☐	☒
						☐	☐
						☐	☐
						☐	☐
						☐	☐

(8) WELL TESTS: Minimum testing time is 1 hour

☐ Pump ☒ Bailer ☐ Air ☐ Flowing Artesian

Yield gal/min	Drawdown	Drill stem at	Time
30	76/66		1 hr.

Temperature of Water 54 Depth Artesian Flow Found

Was a water analysis done? ☐ Yes By whom _____

Did any strata contain water not suitable for intended use? ☐ Too little

☐ Salty ☐ Muddy ☐ Odor ☐ Colored ☐ Other

Depth of strata: