ORIGINAL
File Original, and Duplicate with the STATE ENGINEER, SALEM, OREGON

WATER WELL DRILLERS REPORT
OBSERVATION WELL
STATE OF OREGON

Do Not Fill In — State Well No. 5/1-18 (1) F; State Permit No. App G715

02553
CLAC

(1) OWNER:
Name: Warren Bremer
Address: Rt. 1, Hubbard, Ore.

(2) LOCATION OF WELL:
County: Clackamas — Owner's number, if any: #1
R. F. D. or Street No.
Bearing and distance from section or subdivision corner: 40 feet North of center of section 18 on North 1/4 line. In SW 1/4 of NE 1/4 of 18.

(3) TYPE OF WORK (check):
New well ☒ Deepening ☐ Reconditioning ☐ Abandon ☐
If abandonment, describe material and procedure in Item 11.

(4) PROPOSED USE (check):
Domestic ☐ Industrial ☒ Municipal ☐
Irrigation ☒ Test Well ☐ Other ☐

(5) EQUIPMENT:
Rotary ☐
Cable ☒
Dug Well ☐

(6) CASING INSTALLED:
Threaded ☐ Welded ☒

FROM	ft. to	ft.	Diam.	Gage or Wall
0	86		8"	

Type and size of shoe or well ring: Standard
Describe joint: Butt Weld

If gravel packed

Diameter of Bore	from ft.	to ft.

Size of gravel:

(7) PERFORATIONS:
Type of perforator used: Star
SIZE of perforations: 1 1/2 in., length, by 3/8 in.
FROM 60 ft. to 68 ft. — 5 perf per foot — 5 No. of rows

SCREENS:
Give Manufacturer's Name, Model No. and Size

(8) CONSTRUCTION:
Was a surface sanitary seal provided? ☐ Yes ☐ No To what depth ft.
Were any strata sealed against pollution? ☐ Yes ☐ No
If yes, note depth of strata
FROM ft. to ft.
METHOD OF SEALING

(9) WATER LEVELS:
Depth at which water was first found: 3 ft.
Standing level before perforating: 15 ft.
Standing level after perforating: plus 3 Head ft.

Log Accepted by:
[Signed] Warren Bremer Owner — Dated May 8, 1957

(10) WELL TESTS:
Was a pump test made? ☒ Yes ☐ No If yes, by whom? Driller
Yield: 130 gal./min. with 86 ft. draw down after 4 1/2 hrs.
Artesian flow 18 g.p.m.
Shut-in pressure 1 1/2 lbs. per square inch.
Bailer test ..... g.p.m. with ..... ft. drawdown
Temperature of water 53 Was a chemical analysis made? ☐ Yes ☐ No
Was electric log made of well? ☐ Yes ☐ No

(11) WELL LOG:
Diameter of well, 8 inches. 436 ft.
Total depth 97 ft. Depth of completed well 97 ft.
Formation: *Describe by color, character, size of material and structure, and show thickness of aquifers and the kind and nature of the material in each stratum penetrated, with at least one entry for each change of formation.*

0 ft. to	3 ft.	Top soil
3 "	7 "	Brown clay
7 "	22 "	Brown silt
22 "	31 "	Blue silt
31 "	37 "	Blue clay
37 "	39 "	Brown sand & clay mixed
39 "	50 "	Brown sand, clay & small gravel
50 "	52 "	Blue clay
52 "	56 "	Brown sand
56 "	67 "	Dark sand & gravel (water) Artesian
67 "	75 "	Light blue clay
75 "	83 "	Dark silt
83 "	87 "	Dark shale (soft)
87 "	93 "	Block sand
93 "	97 "	Light blue clay
		Deepened (Dec. 1960) WSB

Ground elevation at well site ..... feet above mean sea level.
Work started April 29 1957. Completed May 8 1957

Well Driller's Statement:
This well was drilled under my jurisdiction and this report is true to the best of my knowledge and belief.

NAME: John W. Beck Well Drilling (Person, firm, or corporation) (Typed or printed)
Address: Rt. 3, Box 45, Canby, Ore.
Driller's well number: 388
[Signed] John W. Beck (Well Driller)
License No. 95 Dated May 8, 1957

No house — 8" — 100 ft deep ??
CK