

RECEIVED JUN 10 1996

CHAC 50587

035/04E/24AD

STATE OF OREGON JUN 10 1996 QWRD WELL I.D.# L01006

(START CARD) # W-69961

WATER SUPPLY WELL REPORT (as required by ORS 473.005) WATER RESOURCES DEPT. SALEM, OREGON Instructions for completing this report are on the last page of this form.

(1) OWNER: Well Number 11-6514-96 Name Springwater Estates #6 Address 21989 S. Woodland Way City Estacada State OR Zip 97023

(2) TYPE OF WORK clean out [ ] New Well [ ] Deepening [X] Alteration (repair/recondition) [ ] Abandonment

(3) DRILL METHOD: [ ] Rotary Air [ ] Rotary Mud [X] Cable [ ] Auger [ ] Other

(4) PROPOSED USE: [ ] Domestic [X] Community [ ] Industrial [ ] Irrigation [ ] Thermal [ ] Injection [ ] Livestock [ ] Other

(5) BORE HOLE CONSTRUCTION: Special Construction approval [ ] Yes [X] No Depth of Completed Well 130 ft. Explosives used [ ] Yes [X] No Type Amount

Table with columns: HOLE Diameter, SEAL Material, From, To, Sacks or pounds. Entry: N/A

How was seal placed: Method [ ] A [ ] B [ ] C [ ] D [ ] E [ ] Other

Backfill placed from ft. to ft. Material Gravel placed from ft. to ft. Size of gravel

(6) CASING/LINER: Table with columns: Diameter, From, To, Gauge, Steel, Plastic, Welded, Threaded. Entry: N/A

Final location of shoe(s)

(7) PERFORATIONS/SCREENS: Table with columns: From, To, Slot size, Number, Diameter, Tele/pipe size, Casing, Liner. Entry: N/A

(8) WELL TESTS: Minimum testing time is 1 hour [ ] Pump [X] Bailer [ ] Air [ ] Flowing Artesian

Table with columns: Yield gal/min, Drawdown, Drill stem at, Time. Entry: 60 gpm, 15 feet, 1 hr.

Temperature of water 53° Depth Artesian Flow Found Was a water analysis done? [ ] Yes By whom Did any strata contain water not suitable for intended use? [ ] Too little [ ] Salty [ ] Muddy [ ] Odor [ ] Colored [ ] Other Depth of strata:

(9) LOCATION OF WELL by legal description: County Clackamas Latitude Longitude Township 3-South N or S Range 4-East E or W. WM. Section 24 SE 1/4 NE 1/4 Tax Lot 700 Lot Block Subdivision Street Address of Well (or nearest address) 21341 S. Park View Lane, Estacada, OR 97023

(10) STATIC WATER LEVEL: 51 ft. below land surface. Date 5/8/96 Artesian pressure lb. per square inch. Date

(11) WATER BEARING ZONES: Depth at which water was first found N/A

Table with columns: From, To, Estimated Flow Rate, SWL. Includes RECEIVED stamp and date AUG 21 1996.

(12) WELL LOG: Ground Elevation

Well had filled in to 120 feet with sand and pea gravel. Cleaned to bottom at 130 feet.

STEINMAN BROS. DRILLING CO. Oregon License No. 1 3023 SE Holly Avenue MILWAUKIE, OREGON 97222 (503) 654-2890

Date started 5/8/96 Completed 5/9/96 (unbonded) Water Well Constructor Certification:

I certify that the work I performed on the construction, alteration, or abandonment of this well is in compliance with Oregon water supply well construction standards. Materials used and information reported above are true to the best of my knowledge and belief. Steinman Bros. WWC Number

Signed Drilling Co. Date

(bonded) Water Well Constructor Certification:

I accept responsibility for the construction, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon water supply well construction standards. This report is true to the best of my knowledge and belief.

Signed Ronald F. McConnell WWC Number 1 (One) Date 5/31/96

RECEIVED

JUN 10 1996

WATER RESOURCES DEPT.  
SALEM, OREGON

RECEIVED

AUG 21 1996

Milwaukie Plywood Corp. Dam  
WATER RESOURCES DEPT.  
SALEM, OREGON

Juanice Layfield, Manager, Springwater Estates Water Systems, Well #11-65/14-96 (#6)

