351EZDC L 02079

DEC - 4 1996

STATE OF OREGON

WATER SUPPLY WELL REPORT Instructions for completing this report are on the last page of this form. WATER RESOURCES DEPT. (START CARD) #_____ (9) LOCATION OF WELL by legal description: Well Number County CLACKAMA Satitude_ Longitude N or S Range / 5 W 1/4 SE 1/4 ____ Block Tax Lot 2500 Lot_ Subdivision (2) TYPE OF WORK New Well ☐ Deepening ★ Alteration (repair/recondition) ☐ Abandonment Street Address of Well (or nearest address) 3187 & LOCUST (3) DRILL METHOD: (10) STATIC WATER LEVEL: Rotary Mud Cable Auger Rotary Air ft. below land surface. Other (4) PROPOSED USE: Date Artesian pressure lb. per square inch. (11) WATER BEARING ZONES: Irrigation Domestic Industrial Community Livestock Other Thermal Injection (5) BORE HOLE CONSTRUCTION: Depth at which water was first found Special Construction approval Yes No Depth of Completed Well **Estimated Flow Rate SWL** From Explosives used Yes No Type Amount HOLE From Sacks or pounds Diameter (12) WELL LOG: How was seal placed: Method \square B Ground Elevation Other _ SWL ft. Material From Material Backfill placed from ft. to Gravel placed from ft. to ft. Size of gravel (6) CASING/LINER: Welded Threaded To Gauge Steel Plastic Diameter \square Casing: \Box Liner: WATER RESOURCES DEPT Final location of shoe(s) SALEM, OREGON (7) PERFORATIONS/SCREENS: Method DRIVE DOWN Perforations Material Screens Type Tele/pipe Slot Casing Liner Number Diameter size Ш П \Box Completed (8) WELL TESTS: Minimum testing time is 1 hour Date started (unbonded) Water Well Constructor Certification: **Flowing** I certify that the work I performed on the construction, alteration, or abandonment Bailer Artesian Air Pump of this well is in compliance with Oregon water supply well construction standards. Time Yield gal/min Drill stem at Materials used and information reported above are true to the best of my knowledge 1 hr and belief. WWC Number Date Signed Temperature of water 53 (bonded) Water Well Constructor Certification: Depth Artesian Flow Found I accept responsibility for the construction, alteration, or abandonment work Yes By whom Was a water analysis done? performed on this well during the construction dates reported above. All work Did any strata contain water not suitable for intended use? performed during this time is in compliance with Oregon water supply well construction standards. This report is true to the best of my knowledge and belief. Salty Muddy Odor Colored Other WWC Number 743 Depth of strata: