

NOTICE TO WATER WELL CONTRACTOR

The original and first copy of this report are to be filed with the

STATE ENGINEER, SALEM 10, OREGON within 30 days from the date of well completion.

RECEIVED

OCT 29 1965

WATER WELL REPORT

STATE OF OREGON

(Please type or print)

State Well No.

2/3-27 B

State Permit No.

(1) OWNER:

Name

Address

(2) LOCATION OF WELL:

County Clackamas Driller's well number

1/4 1/4 Section T. 2 S R. 3 E W.M.

Bearing and distance from section or subdivision corner

well located 70' E. and 20' N. of tract described on separate sheet. S.W. corner of

(3) TYPE OF WORK (check):

Well ☒ Deepening ☐ Reconditioning ☐ Abandon ☐
If abandonment, describe material and procedure in Item 12.

(4) PROPOSED USE (check):

Domestic ☒ Industrial ☐ Municipal ☐
Irrigation ☐ Test Well ☐ Other ☐

(5) TYPE OF WELL:

Rotary ☐ Driven ☐
Cable ☒ Jetted ☐
Dug ☐ Bored ☐

(6) CASING INSTALLED:

Threaded ☐ Welded ☒

6" Diam. from 0 ft. to 96 ft. Gage 17 lb.

" Diam. from ft. to ft. Gage

" Diam. from ft. to ft. Gage

(7) PERFORATIONS:

Perforated? ☐ Yes ☒ No

Type of perforator used

Size of perforations in. by in.

perforations from ft. to ft.

perforations from ft. to ft.

perforations from ft. to ft.

perforations from ft. to ft.

perforations from ft. to ft.

(8) SCREENS:

Well screen installed? ☐ Yes ☐ No

Manufacturer's Name

Type Model No.

Diam. Slot size Set from ft. to ft.

Diam. Slot size Set from ft. to ft.

(9) CONSTRUCTION:

Well seal—Material used in seal CementDepth of seal To 30' ft. Was a packer used? noDiameter of well bore to bottom of seal 8" in. 426'Were any loose strata cemented off? ☐ Yes ☒ No DepthWas a drive shoe used? ☒ Yes ☐ NoWas well gravel packed? ☐ Yes ☒ No Size of gravel:

Gravel placed from ft. to ft.

Did any strata contain unusable water? ☐ Yes ☐ No

Type of water? Depth of strata

Method of sealing strata off

(10) WATER LEVELS:

Static level 7.5' ft. below land surface Date Oct. 20, 65

Artesian pressure lbs. per square inch Date

(11) WELL TESTS:

Drawdown is amount water level is lowered below static level

Was a pump test made? ☐ Yes ☒ No If yes, by whom?Yield: 10 gal./min. with ft. drawdown after hrs.

" " " "

" " " "

Bailer test 10 gal./min. with 10 ft. drawdown after 1 hrs.

Artesian flow g.p.m. Date

Temperature of water Was a chemical analysis made? ☐ Yes ☒ No

(12) WELL LOG:

Diameter of well below casing 6"Depth drilled 98' ft. Depth of completed well 98' ft.

Formation: Describe by color, character, size of material and structure, and show thickness of aquifers and the kind and nature of the material in each stratum penetrated, with at least one entry for each change of formation.

MATERIAL	FROM	TO
Top Soil	0	8
Gray yellow & some rock	8	14
Boulders	14	18
Cobble rock	18	45
Decomposed rock	45	52
Cemented gravel	52	77
Loose sand & gravel	77	98

Work started 4-8-65 19 Completed 10-15 1965Date well drilling machine moved off of well Oct. 21 1965

(13) PUMP:

Manufacturer's Name Fairbanks MorseType: submersible H.P. 2

Water Well Contractor's Certification:

This well was drilled under my jurisdiction and this report is true to the best of my knowledge and belief.

NAME O. E. Jannsen Drilling Co.
(Person, firm or corporation) (Type or print)

Address Box 138 Clackamas Ore.Drilling Machine Operator's License No. 237

[Signed] O. E. Jannsen
(Water Well Contractor)

Contractor's License No. 3 Date Oct. 21, 1965

(USE ADDITIONAL SHEETS IF NECESSARY)

The following described property is real property of Gearold L. Sliger and Ethel C. Sliger, husband and wife:

Situated in the County of Clackamas and State of Oregon to-wit:

~~Attest~~ A tract of land in the Joseph S. Church D.L.C. No. 46, in T. 2 S., R. 3 E., of the W.M., in the County of Clackamas and State of Oregon, more particularly described as follows, to-wit;

Beginning at the southwest corner of the said Joseph S. Church D.L.C.; running thence East 228.71 feet tracing the south line of said claim to a point; thence North and parallel to the west line of said claim 208.71 feet to a point; thence West and parallel to the south line of said claim 228.71 feet to an iron pipe on the west line of said claim; thence South tracing the west line of said claim 208.71 feet to the place of beginning.

RECEIVED
OCT 29 1965
STATE ENGINEER
CLACKAMAS, OREGON