WATER SUPPLY WELL REPORT

WELL ID # 39120

(START CARD) # 131498

(as required by ORS 537.765)

Instructions for completing this report are on the last page of this form

SKYLES DRILLING, INC. (9) LOCATION OF WELL by legal description: (1) OWNER: Well Number: 01 Longitude Clackamas Latitude Forest Park Mobile Home Village Name Township 3SOUTHN or S. Range E or W. of WM. 1EAST Address 18830 S. Hwy. 99E. Section 2 SW 1/4 SF 1/4 State OR Zip 97045 City **Oregon City** Tax lot 1600 Block Lot Street Address of Well (or nearest address) 18830 S. Hwy. 99E., (2) TYPE OF WORK: Oregon City, OR New Well Deepening X Alteration (repair/recondition) | | Abandonment (10) STATIC WATER LEVEL: (3) DRILL METHOD: ft, below land surface Date 6/22/00 21 Artesian pressure lb. per square inch. Date Rotary Mud Cable Auger Rotary Air X Other Pump Hoist (11) WATER BEARING ZONES: (4) PROPOSED USE: Depth at which water was first found N/A Irrigation X Community Domestic Undustrial Injection Other From To Estimated Flow Rate SWL Livestock Thermal (5) BORE HOLE CONSTRUCTION: Special Construction approval [| Yes | X|No Depth of Completed Well 125 Amount Explosives used | Yes |X|No HOLE SEAL Amount (12) WELL LOG: To sacks or pounds From Material Diameter From Ground elevation 125 No Change 6 Material From Τo SWL This is a casing extension only Skyles Drilling Inc. 1169 Molalla Ave. Oregon City, OR 97045 How was seal placed: Method | A |C | |D | |E | |B 503-656-2683 Other ft. to ft. Material Backfill placed from ft. Size of gravel Gravel placed from ft. to (6) CASING/LINER: Plastic Welded Threaded То Gauge Steel Diameter 2 .250 6 Casing N/A Liner: WATER RESOURCES DEPT SALEM, OREGON Final location of shoe(s) N/A (7) PERFORATIONS/SCREENS: Method Perforations Material Type Screens Slot Tele/pipe Casing Number Diameter Liner То From size None Date started 6/22/00 Completed 6/22/00 (unbonded) Water Well Constructor Certification: I certify that the work I performed on the construction, alteration, or abandonment of this well is in compliance with Oregon water supply well construction standards. (8) WELL TESTS: Minimum testing time is 1 hour Materials used and information reported above are true to my best knowledge and belief. Flowing Artesian Air Bailer Pump Time Signed Drill stem at Yield gal/min Drawdown 1 hr. N/A (bonded) Water Well Constructor Certification: Laccept responsibility for the construction, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon water supply well Depth Artesian Flow found Temperature of Water construction standards. This report is true to the best of my knowledge and belief. Was a water analysis done? | Yes By whom

Colored

Other

| |Too little

Did any strata contain water not suitable for intended use?

Odor

Muddy

Salty Depth of strata: Signed

WWC Number 1592

Date 6-22-2000