CLAC 67205

Clac 67205

STATE OF OREGON
WATER SUPPLY WELL REPORT
(as required by ORS 537.765)

WELL I.D. # L 62487

START CARD # 1011223

Instructions for completing this report are on the last page of this form.

(1) LAND OWNER Well Number 2
Name Luke Howard
Address 36596 S Wilhoit Rd
City Molalla State OR Zip 97038

(2) TYPE OF WORK ☐ New Well Hydrofracturing
☐ Deepening ☐ Alteration (repair/recondition) ☐ Abandonment ☐ Conversion

(3) DRILL METHOD
☐ Rotary Air ☐ Rotary Mud ☐ Cable ☐ Auger ☐ Cable Mud
☒ Other Dual packers w/water pressure

(4) PROPOSED USE
☒ Domestic ☐ Community ☐ Industrial ☐ Irrigation
☐ Thermal ☐ Injection ☐ Livestock ☐ Other

(5) BORE HOLE CONSTRUCTION Special Construction: ☐ Yes ☐ No
Depth of Completed Well ____ ft. No change
Explosives used: ☐ Yes ☐ No Type ____ Amount ____

BORE HOLE Diameter	From	To	SEAL Material	From	To	Sacks or Pounds

How was seal placed: Method ☐ A ☐ B ☐ C ☐ D ☐ E
☐ Other
Backfill placed from ____ ft. to ____ ft. Material
Gravel placed from ____ ft. to ____ ft. Size of gravel

(6) CASING/LINER No change

	Diameter	From	To	Gauge	Steel	Plastic	Welded	Threaded
Casing:					☐	☐	☐	☐
					☐	☐	☐	☐
					☐	☐	☐	☐
					☐	☐	☐	☐
Liner:					☐	☐	☐	☐
					☐	☐	☐	☐

Drive Shoe used ☐ Inside ☐ Outside ☐ None
Final location of shoe(s)

(7) PERFORATIONS/SCREENS No change
☐ Perforations Method
☐ Screens Type ____ Material

From	To	Slot Size	Number	Diameter	Tele/pipe size	Casing	Liner
						☐	☐
						☐	☐
						☐	☐
						☐	☐
						☐	☐

(8) WELL TESTS: Minimum testing time is 1 hour
☒ Pump ☐ Bailer ☐ Air ☐ Flowing Artesian

Yield gal/min	Drawdown	Drill stem at	Time
~~2X45X~~			
5 gpm	67'		9/08/10

Temperature of water same Depth Artesian Flow Found
Was a water analysis done? ☐ Yes By whom
Did any strata contain water not suitable for intended use? ☐ Too little
☐ Salty ☐ Muddy ☐ Odor ☐ Colored ☐ Other
Depth of strata:

RECEIVED DEC 03 2010 WATER RESOURCES DEPT SALEM, OREGON

RECEIVED OCT 29 2010 WATER RESOURCES DEPT SALEM, OREGON

(9) LOCATION OF WELL (legal description)
County Clackamas
Tax Lot 1801 Lot
Township 6S N or S Range 2E E or W WM
Section 5 NW 1/4 SW 1/4
Lat 45 ° 4 ' 39" or ____ (degrees or decimal)
Long 122 ° 35 ' 46" or ____ (degrees or decimal)
Street Address of Well (or nearest address) 36596 S Wilhoit Rd
Molalla, OR 97038

(10) STATIC WATER LEVEL
____ ft. below land surface. Date
34 ft. below land surface. Date 8/30/10
Artesian pressure ____ lb. per square inch Date

(11) WATER BEARING ZONES
Depth at which water was first found

From	To	Estimated Flow Rate	SWL

(12) WELL LOG Ground Elevation

Material	From	To	SWL
Hydrofracturing	63	168	
packer locations	168	273	
	273	378	
	378	483	
	483	588	
	588	693	
	693	798	
	798	bottom	

RECEIVED OCT 01 2010 WATER RESOURCES DEPT SALEM, OREGON

Date Started 8/30/10 Completed 8/31/10

(unbonded) Water Well Constructor Certification
I certify that the work I performed on the construction, deepening, alteration, or abandonment of this well is in compliance with Oregon water supply well construction standards. Materials used and information reported above are true to the best of my knowledge and belief.

WWC Number ____ Date

Signed

(bonded) Water Well Constructor Certification
I accept responsibility for the construction, deepening, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon water supply well construction standards. This report is true to the best of my knowledge and belief.

WWC Number 1374 Date 9-29-10
Signed Lynn Bartholomew

CLAC 67205

STATE OF OREGON
WATER SUPPLY WELL REPORT
(as required by ORS 537.765)

WELL I.D. # L 62487

START CARD # 1011223

Instructions for completing this report are on the last page of this form.

(1) LAND OWNER Well Number 2
Name Luke Howard
Address 36596 S Wilhoit Rd
City Molalla State OR Zip 97038

(2) TYPE OF WORK ☐ New Well Hydrofracturing
☐ Deepening ☐ Alteration (repair/recondition) ☐ Abandonment ☐ Conversion

(3) DRILL METHOD
☐ Rotary Air ☐ Rotary Mud ☐ Cable ☐ Auger ☐ Cable Mud
☒ Other Dual packers w/water pressure

(4) PROPOSED USE
☒ Domestic ☐ Community ☐ Industrial ☐ Irrigation
☐ Thermal ☐ Injection ☐ Livestock ☐ Other

(5) BORE HOLE CONSTRUCTION Special Construction: ☐ Yes ☐ No
Depth of Completed Well ____ ft. No change
Explosives used: ☐ Yes ☐ No Type ____ Amount ____

BORE HOLE Diameter	From	To	SEAL Material	From	To	Sacks or Pounds

How was seal placed: Method ☐ A ☐ B ☐ C ☐ D ☐ E
☐ Other
Backfill placed from ____ ft. to ____ ft. Material
Gravel placed from ____ ft. to ____ ft. Size of gravel

(6) CASING/LINER No change

	Diameter	From	To	Gauge	Steel	Plastic	Welded	Threaded
Casing:					☐	☐	☐	☐
					☐	☐	☐	☐
					☐	☐	☐	☐
					☐	☐	☐	☐
Liner:					☐	☐	☐	☐
					☐	☐	☐	☐

Drive Shoe used ☐ Inside ☐ Outside ☐ None
Final location of shoe(s)

(7) PERFORATIONS/SCREENS No change
☐ Perforations Method
☐ Screens Type ____ Material

From	To	Slot Size	Number	Diameter	Tele/pipe size	Casing	Liner
						☐	☐
						☐	☐
						☐	☐
						☐	☐
						☐	☐

(8) WELL TESTS: Minimum testing time is 1 hour
☒ Pump ☐ Bailer ☐ Air ☐ Flowing Artesian

Yield gal/min	Drawdown	Drill stem at	Time
2.45			

Temperature of water same Depth Artesian Flow Found
Was a water analysis done? ☐ Yes By whom
Did any strata contain water not suitable for intended use? ☐ Too little
☐ Salty ☐ Muddy ☐ Odor ☐ Colored ☐ Other
Depth of strata:

(9) LOCATION OF WELL (legal description)
County Clackamas
Tax Lot 1801 Lot
Township 6S N or S Range 2E E or W WM
Section 5 NW 1/4 SW 1/4
Lat 45 ° 4 ' 39" or ___ (degrees or decimal)
Long 122 ° 35 ' 46" or ___ (degrees or decimal)
Street Address of Well (or nearest address) 36596 S Wilhoit Rd
Molalla, OR 97038

(10) STATIC WATER LEVEL
____ ft. below land surface. Date
34 ft. below land surface. Date 8/30/10
Artesian pressure ____ lb. per square inch Date

(11) WATER BEARING ZONES
Depth at which water was first found

From	To	Estimated Flow Rate	SWL

(12) WELL LOG Ground Elevation

Material	From	To	SWL
Hydrofracturing	63	168	
packer locations	168	273	
	273	378	
	378	483	
	483	588	
	588	693	
	693	798	
	798	bottom	

RECEIVED
OCT 01 2010
WATER RESOURCES DEPT
SALEM, OREGON

Date Started 8/30/10 Completed 8/31/10

(unbonded) Water Well Constructor Certification
I certify that the work I performed on the construction, deepening, alteration, or abandonment of this well is in compliance with Oregon water supply well construction standards. Materials used and information reported above are true to the best of my knowledge and belief.

WWC Number ____ Date ____

Signed ____

(bonded) Water Well Constructor Certification
I accept responsibility for the construction, deepening, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon water supply well construction standards. This report is true to the best of my knowledge and belief.

WWC Number 1374 Date 9-29-10
Signed Lynn Bartholomew

ORIGINAL – WATER RESOURCES DEPARTMENT FIRST COPY – CONSTRUCTOR SECOND COPY – CUSTOMER 06/16/2004