

STATE OF OREGON
WATER SUPPLY WELL REPORT

(as required by ORS 537.765 & OAR 690-205-0210)

Westerberg Drilling, Inc.
36728 S. Kropf Rd.
Malilla, OR 97038

WELL I.D. LABEL# 116771

START CARD # 212273

ORIGINAL LOG #

(1) LAND OWNER

Owner Well I.D.

First Name Mike & Cheryl

Last Name Bratcher

Company

Address 4128 SW Britton Drive

City Gresham

State OR

Zip 97080

(2) TYPE OF WORK

☒ New Well ☐ Deepening ☐ Conversion☐ Alteration (complete 2a & 10) ☐ Abandonment (complete 5a)

(2a) PRE-ALTERATION

Casing: Dia + From To Gauge Stl Plstc Wld Thrd

Material From To Amt sacks/lbs

Seal:

(3) DRILL METHOD

☐ Rotary Air ☐ Rotary Mud ☒ Cable ☐ Auger ☐ Cable Mud☐ Reverse Rotary ☐ Other

(4) PROPOSED USE

☒ Domestic ☒ Irrigation ☐ Community☐ Industrial/Commercial ☐ Livestock ☐ Dewatering☐ Thermal ☐ Injection ☐ Other

(5) BORE HOLE CONSTRUCTION

Special Standard ☐ (Attach copy)

Depth of Completed Well 18 ft.

BORE HOLE

Dia	From	To	Material	From	To	Amt	sacks/lbs
10	0	18	Bentonite	0	18	12	S
						Calculated	7.4
						Calculated	

How was seal placed:

Method

☐ A☐ B☐ C☐ D☐ E☒ Other bent. placed dry

Backfill placed from ft. to ft. Material

Filter pack from ft. to ft. Material Size

Explosives used: ☐ Yes Type Amount

(5a) ABANDONMENT USING UNHYDRATED BENTONITE

Proposed Amount Pounds Actual Amount Pounds

(6) CASING/LINER

Casing	Liner	Dia	+	From	To	Gauge	Stl	Plstc	Wld	Thrd
☒	☐	6	☒	2	18	.250	☒	☐	☒	☐
☐	☐		☐				☐	☐	☐	☐
☐	☐		☐				☐	☐	☐	☐
☐	☐		☐				☐	☐	☐	☐
☐	☐		☐				☐	☐	☐	☐

Shoe ☐ Inside ☒ Outside ☐ Other Location of shoe(s) 18Temp casing ☐ Yes Dia From To

(7) PERFORATIONS/SCREENS

Perforations Method

Screens Type

Material

Perf/S creen	Casing/ Liner	Screen Dia	From	To	Scrn/slot width	Slot length	# of slots	Tele/ pipe size

(8) WELL TESTS: Minimum testing time is 1 hour

☐ Pump ☐ Bailer ☐ Air ☐ Flowing Artesian

Yield gal/min Drawdown Drill stem/Pump depth Duration (hr)

Temperature °F Lab analysis ☐ Yes ByWater quality concerns? ☐ Yes (describe below) TDS amount

From	To	Description	Amount	Units

(9) LOCATION OF WELL (legal description)

County CLACKAMAS Twp 1 S N/S Range 4 E E/W WM

Sec 32 NW 1/4 of the NW 1/4 Tax Lot 700

Tax Map Number Lot

Lat " or DMS or DD

Long " or DMS or DD

☒ Street address of well ☐ Nearest address

30330 Hayley Rd SE, Boring, OR 97009

(10) STATIC WATER LEVEL

	Date	SWL (psi)	+	SWL (ft)
Existing Well / Pre-Alteration				
Completed Well				

Flowing Artesian? ☐ Dry Hole? ☒

WATER BEARING ZONES

Depth water was first found

SWL Date From To Est Flow SWL (psi) + SWL (ft)

(11) WELL LOG

Ground Elevation

Material	From	To
top soil	0	1
clay tan yellow	1	17
clay grey	17	18
Dry Hole		
Well is temporarily abandoned pending a permit amendment.		
RECEIVED BY OWRD		
AUG 21 2015		
SALEM, OR		

Date Started 08-12-2015

Completed 08-12-2015

(unbonded) Water Well Constructor Certification

I certify that the work I performed on the construction, deepening, alteration, or abandonment of this well is in compliance with Oregon water supply well construction standards. Materials used and information reported above are true to the best of my knowledge and belief.

License Number Date

Signed

(bonded) Water Well Constructor Certification

I accept responsibility for the construction, deepening, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon water supply well construction standards. This report is true to the best of my knowledge and belief.

License Number 688 Date 08-17-2015

Signed Steven M. Stutts

Contact Info (optional)