

CLAC 74970

STATE OF OREGON

WELL ID # L 132840

WATER SUPPLY WELL REPORT

SKYLES DRILLING, INC.

START CARD # W1042562

(as required by ORS 537.765)

Instructions for completing this report are on the last page of this form

503-656-2683

CLAC-74970

(1) OWNER:

Well Number: 01

Name Nels Iverson
Address 33085 S Meridian Rd
City Woodburn State OR Zip 97071

(2) TYPE OF WORK:

New Well Deepening Alteration (repair/recondition) Abandonment

(3) DRILL METHOD:

Rotary Air Rotary Mud Cable Auger Other

(4) PROPOSED USE:

Domestic Community Industrial Irrigation
Thermal Injection Livestock Other

(5) BORE HOLE CONSTRUCTION:

Special Construction approval Yes No Depth of Completed Well 156 ft.
Explosives used Yes No Type Amount

Table with columns: HOLE Diameter, From, To, SEAL Material, From, To, Amount sacks or pounds. Row 1: 8, Unchanged.

How was seal placed: Method A B C D E
Backfill placed from ft. to ft. Material
Gravel placed from ft. to ft. Size of gravel

(6) CASING/LINER:

Table with columns: Diameter, From, To, Gauge, Steel, Plastic, Welded, Threaded. Rows for Casing and Liner.

Drive Shoe used Inside Outside None
Final location of shoe(s) N/A

(7) PERFORATIONS/SCREENS:

Table with columns: From, To, Slot size, Number, Diameter, Tele/pipe size, Casing, Liner. Includes rows for Perforations and Screens.

(8) WELL TESTS: Minimum testing time is 1 hour

Pump Bailer Air Flowing Artesian

Table with columns: Yield gal/min, Drawdown, Drill stem at, Time. Rows for 100+ and 75+ yield, and TDS Amount 136 ppm.

Temperature of Water 56.1 Depth Artesian Flow found
Was a water analysis done? Yes By whom SDI, Iron 3 ppm
Did any strata contain water not suitable for intended use? Too little
Salty Muddy Odor Colored Other
Depth of strata:

(9) LOCATION OF WELL by legal description:

County Clackamas Latitude Longitude
Township 5SOUTH N or S. Range 1WEST E or W. of WM.
Section 13 NE 1/4 NW 1/4
Tax lot 00800 Lot Block Subdivision
Street Address of Well (or nearest address) 32221 S Meridian Rd, Woodburn, OR

(10) STATIC WATER LEVEL:

37 ft. below land surface. Date 4/26/2019
Artesian pressure lb. per square inch. Date

(11) WATER BEARING ZONES:

Depth at which water was first found N/A

Table with columns: From, To, Estimated Flow Rate, SWL.

(12) WELL LOG:

Table with columns: Material, From, To, SWL. Includes text: Clean-out Only of CLAC 2083, SKYLES DRILLING, INC., 503-656-2683, RECEIVED, MAY 16 2019, OWRD.

Date started 4/26/2019 Completed 4/26/2019

(unbonded) Water Well Constructor Certification:

I certify that the work I performed on the construction, alteration, or abandonment of this well is in compliance with Oregon water supply well construction standards. Materials used and information reported above are true to the best of my knowledge and belief.

Signed [Signature] WWC Number 1884
Date 5/3/2019
Skyles Drilling, Inc.

(bonded) Water Well Constructor Certification:

I accept responsibility for the construction, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon water supply well construction standards. This report is true to the best of my knowledge and belief.

Signed [Signature] WWC Number 2006
Date 5/3/2019
Skyles Drilling, Inc.