Amd 11/17/2026

CLAT 53264

10-22-2009

STATE OF OREGON
WATER SUPPLY WELL REPORT
(as required by ORS 537.765 & OAR 690-205-0210)

WELL LABEL # L 59017

START CARD # 1007878

(1) LAND OWNER

Owner Well I.D. PW #1

First Name _____ Last Name _____

Company City of Gearhart

Address 698 Pacific Way

City Gearhart State OR Zip 97138

(2) TYPE OF WORK

☒ New Well ☐ Deepening ☐ Conversion ☐ Alteration (repair/recondition) ☐ Abandonment

(3) DRILL METHOD

☐ Rotary Air ☐ Rotary Mud ☐ Cable ☐ Auger ☐ Cable Mud ☒ Reverse Rotary ☐ Other

(4) PROPOSED USE

☐ Domestic ☐ Irrigation ☒ Community ☐ Industrial/ Commericial ☐ Livestock ☐ Dewatering ☐ Thermal ☐ Injection ☐ Other

(5) BORE HOLE CONSTRUCTION

Special Standard ☐ (Attach copy)

Depth of Completed Well 119.00 ft.

BORE HOLE Dia	From	To	SEAL Material	From	To	Amt	sacks/ lbs
16	0	119	Cement	0	76	68	S

How was seal placed: Method ☐ A ☐ B ☒ C ☐ D ☐ E

☐ Other

Backfill placed from ft. to ft. Material

Filter pack from 76 ft. to 119 ft. Material Silica Sand Size 10/20

Explosives used: ☐ Yes Type Amount

(6) CASING/LINER

Casing	Liner	Dia	+	From	To	Gauge	Stl	Plstc	Wld	Thrd
●	○	10	☒	3	84	0.375	●	○	☒	☐
●	○	10	☐	114	119	0.375	●	○	☒	☐
○	○		☐				○	○	☐	☐
○	○		☐				○	○	☐	☐
○	○		☐				○	○	☐	☐

Shoe ☐ Inside ☐ Outside ☐ Other Location of shoe(s)

Temp casing ☐ Yes Dia From To

(7) PERFORATIONS/SCREENS

Perforations Method

Screens Type Spiral Wrap Material 304 SS

Perf/Screen	Casing/ Liner	Screen Dia	From	To	Scrn/slot width	Slot length	# of slots	Tele/ pipe size
Screen		10	84	114	.035			

(8) WELL TESTS: Minimum testing time is 1 hour

● Pump ○ Bailer ○ Air ○ Flowing Artesian

Yield gal/min	Drawdown	Drill stem/Pump depth	Duration (hr)
125	41	84	24

Temperature 54 °F Lab analysis ☒ Yes By Consultant

Water quality concerns? ☐ Yes (describe below)

From	To	Description	Amount	Units

(9) LOCATION OF WELL (legal description)

County Clatsop Twp 6.00 N N/S Range 10.00 W E/W WM

Sec 4 SW 1/4 of the SE 1/4 Tax Lot 100

Tax Map Number Lot

Lat ° 0 ' " or DMS or DD

Long ° 0 ' " or DMS or DD

○ Street address of well ● Nearest address

6th Ave and Marion Street, Gearhart, Oregon

(10) STATIC WATER LEVEL

	Date	SWL(psi)	+	SWL(ft)
Existing Well / Predeepening				
Completed Well	09-10-2009			27

Flowing Artesian? ☐ Dry Hole? ☐

WATER BEARING ZONES Depth water was first found 8'

SWL Date	From	To	Est Flow	SWL(psi)	+	SWL(ft)
08-27-2009	20	119	125			25

(11) WELL LOG

Ground Elevation

Material	From	To
Med/Coarse/Fine Sands	0	65
Med/Coarse/Fine Sands with sea shells	65	75
Med/Coarse/Fine Sands, dark wood with trace org.	75	115
Dark gray sand with clay, dense	115	118
Hard, fractured basalt	118	119

RECEIVED
MAR 25 2010
WATER RESOURCES DEPT
SALEM, OREGON

Date Started 08-27-2009 Completed 10-21-2009

(unbonded) Water Well Constructor Certification

I certify that the work I performed on the construction, deepening, alteration, or abandonment of this well is in compliance with Oregon water supply well construction standards. Materials used and information reported above are true to the best of my knowledge and belief.

License Number 1702 Date 10-22-2009

Electronically Filed

Signed RUSTY R OTTO (E-filed)

(bonded) Water Well Constructor Certification

I accept responsibility for the construction, deepening, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon water supply well construction standards. This report is true to the best of my knowledge and belief.

License Number 1523 Date 10-22-2009

Electronically Filed

Signed ROBERT STADELI (E-filed)

Contact Info (optional)

ORIGINAL - WATER RESOURCES DEPARTMENT

THIS REPORT MUST BE SUBMITTED TO THE WATER RESOURCES DEPARTMENT WITHIN 30 DAYS OF COMPLETION OF WORK

Form Version: 0.95