## STATE OF OREGON WATER SUPPLY WELL REPORT (as required by ORS 537.765)

## **COLU 55007**

## (as required by ORS 537.765) SKYLES DRILLING, INC. Instructions for completing this report are on the last page of this form

START CARD # W1027199

(1) OWNER: Well Number: 01	<b>56-2683</b>   (9) LOCATION OF WELL by legal description:
Name Columbia Hill HOA	County Columbia Latitude Longitude
Address 2255 Tioga Dr	
City Menlo Park State CA Zip 94025	Tax lot 2400 Lot Block Subdivision
(2) TYPE OF WORK:	Street Address of Well (or nearest address) 31900 Callahan Rd,
New Well Deepening X Alteration (repair/recondition) Abandonment	Scappoose, OR
(3) DRILL METHOD:	(10) STATIC WATER LEVEL:
Rotary Air Rotary Mud Cable Auger	199 ft. below land surface. Date 7/15/2015 Artesian pressure lb. per square inch. Date
X Other Pump Hoist	(11) WATER BEARING ZONES:
(4) PROPOSED USE:	Depth at which water was first found N/A
X Domestic Community Industrial Irrigation	Deput at which water was hist found N/A
Thermal Injection Livestock Other	From To Estimated Flow Rate SWL
(5) BORE HOLE CONSTRUCTION:	
Special Construction approval Yes X No Depth of Completed Well 303 ft.	
Explosives used Yes X No Type Amount	
HOLE SEAL Amount	(12) WELL LOG:
Diameter From To Material From To sacks or pounds 6 Unchanged	Ground elevation
	Material From To SWL
	Clean-out well installed liner w/ shale trap.
	Note: 4" certilock 6'-126'
	4" Flush Thread 126'-246'
How was seal placed: Method A B C D E Other	
Backfill placed from ft. to ft. Material	Existing 5" liner is in well from 205 to 308'
Gravel placed from ft. to ft. Size of gravel	Columbia_3174
(6) CASING/LINER: Diameter From To Gauge Steel Plastic Welded Threaded	
Casing: 6 +2.7 218.7 .250 X	
Existng	SKYLES DRILLING, INC.
Shale Trap 100'	503-656-2683
Liner: 4 6 126 Sch40 X	
4 126 246 Sch40 X	
Drive Shoe used Inside Outside None Final location of shoe(s) N/A	RECEIVED BY OWRD
(7) PERFORATIONS/SCREENS:	SEP 1 1 2015
X Perforations Method Saw Screens Type Material	
Slot Tele/pipe	SALEM, OR
From To size Number Diameter size Casing Liner 227 245 1/8x4 308	GALLIVI, OH
221 243 11004 300	
	Date started 8/15/2015 Completed 8/15/2015
	(unbonded) Water Well Constructor Certification:
	I certify that the work I performed on the construction, alteration, or abandon- ment of this well is in compliance with Oregon water supply well construction
(8) WELL TESTS: Minimum testing time is 1 hour	standards. Materials used and information reported above are true to the best of my
Pump Bailer Air Flowing Artesian	knowledge and belief.
Yield gal/min Drawdown Drill stem at Time	Signed WWC Number Date
N/A	
7.747.7	(bonded) Water Well Constructor Certification:
	l accept responsibility for the construction, alteration, or abandonment work
Temperature of Water Depth Artesian Flow found	performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon water supply well
Was a water analysis done? Yes By whom	construction standards. This report is true to the best of my knowledge and belief.
Did any strata contain water not suitable for intended use? Too little	WWC Number 1592
Salty Muddy Odor Colored Other  Depth of strata:	Signed Skyles Drilling, Inc. Date 9/3/2015
	I SKYIES DITHING, INC. /