

SEP 18 2001

STATE OF OREGON
WATER SUPPLY WELL REPORT WATER RESOURCES DEPT.
(as required by ORS 537.765) SALEM, OREGON
Instructions for completing this report are on the last page of this form.

WELL I.D. # 52461
START CARD # 105680

(1) LAND OWNER Well Number 1
Name JAYNE MILLER + LORI RODMAN
Address 88908 GREYNA GREEN LANE
City BANDON State OR Zip 97211

(2) TYPE OF WORK
☒ New Well ☐ Deepening ☐ Alteration (repair/recondition) ☐ Abandonment

(3) DRILL METHOD:
☒ Rotary Air ☐ Rotary Mud ☐ Cable ☐ Auger
☐ Other _____

(4) PROPOSED USE:
☒ Domestic ☐ Community ☐ Industrial ☐ Irrigation
☐ Thermal ☐ Injection ☐ Livestock ☐ Other _____

(5) BORE HOLE CONSTRUCTION:
Special Construction approval ☐ Yes ☒ No Depth of Completed Well 48 ft.
Explosives used ☐ Yes ☒ No Type _____ Amount _____

HOLE			SEAL			
Diameter	From	To	Material	From	To	Sacks or pounds
10"	0	19	BEATON	0	19	13
6"	19	48				

How was seal placed: Method ☐ A ☐ B ☐ C ☐ D ☐ E
☒ Other POURED DRY
Backfill placed from _____ ft. to _____ ft. Material _____
Gravel placed from _____ ft. to _____ ft. Size of gravel _____

(6) CASING/LINER:

	Diameter	From	To	Gauge	Steel	Plastic	Welded	Threaded
Casing:	6"	72	43	1250	☒	☐	☒	☐
					☐	☐	☐	☐
					☐	☐	☐	☐
					☐	☐	☐	☐
Liner:					☐	☐	☐	☐
					☐	☐	☐	☐

Drive Shoe used ☐ Inside ☐ Outside ☐ None
Final location of shoe(s) _____

(7) PERFORATIONS/SCREENS:

☐ Perforations Method _____
☒ Screens Type TELL Material STAINLESS

From	To	Slot size	Number	Diameter	Tele/pipe size	Casing	Liner
43	48	.010	5'	5 3/4"	6	☒	☐
						☐	☐
						☐	☐
						☐	☐

(8) WELL TESTS: Minimum testing time is 1 hour

Yield gal/min	Drawdown	Drill stem at	Flowing Time
16	16	48	1 hr.

Temperature of water 52° Depth Artesian Flow Found _____
Was a water analysis done? ☐ Yes By whom _____
Did any strata contain water not suitable for intended use? ☐ Too little
☐ Salty ☐ Muddy ☐ Odor ☐ Colored ☐ Other _____
Depth of strata: _____

(9) LOCATION OF WELL by legal description:
County COOS Latitude _____ Longitude _____
Township 28 N or S Range 17 E or W M.
Section 21 SE 1/4 NE 1/4
Tax Lot 17 Lot #1 Block _____ Subdivision _____

Street Address of Well (or nearest address) 88908 GREYNA GREEN LANE BANDON OR 97211

(10) STATIC WATER LEVEL:
8 ft. below land surface. Date 8-22-01
Artesian pressure _____ lb. per square inch Date _____

(11) WATER BEARING ZONES:
Depth at which water was first found _____

From	To	Estimated Flow Rate	SWL
8	48	16 16	8

(12) WELL LOG:
Ground Elevation _____

Material	From	To	SWL
TOP SOIL	0	1	
BROWN CLAY	1	4	
ORANGE SANDY CLAY	4	15	
TAN SANDY CLAY w/ GRAVEL	15	22	
BROWN SANDY CLAY w/ GRAVEL	22	27	
STICKY BROWN CLAY w/ SAND + GRAVEL	27	31	
ORANGE SANDY CLAY	31	36	
TAN SANDY CLAY	36	48	

Date started 8-21-01 Completed 8-22-01

(unbonded) Water Well Constructor Certification:
I certify that the work I performed on the construction, alteration, or abandonment of this well is in compliance with Oregon water supply well construction standards. Materials used and information reported above are true to the best of my knowledge and belief.
Signed _____ Date _____ WWC Number _____

(bonded) Water Well Constructor Certification:
I accept responsibility for the construction, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon water supply well construction standards. This report is true to the best of my knowledge and belief.
Signed [Signature] Date 9-17-01 WWC Number 1624