STATE OF OREGON

# WATER WELL REPORT

(as required by ORS 537.765)

CROO 2141

RECEIVED DEC - 1987 WATER RESOURCES DEPT SALEM, OREGON

RECEIVED JAN - 6 1988 WATER RESOURCES DEPT SALEM, OREGON

15S/16E-6aa

## (1) OWNER:

Well Number: CROOK 2141

Name First Interstate Bank OREGON

Address PO Box 520

City Prineville State Or Zip 97754

## (2) TYPE OF WORK:

☒ New Well ☐ Deepen ☐ Recondition ☐ Abandon

## (3) DRILL METHOD

☐ Rotary Air ☐ Rotary Mud ☒ Cable

☐ Other

## (4) PROPOSED USE:

☒ Domestic ☐ Community ☐ Industrial ☐ Irrigation

☐ Thermal ☒ Injection ☐ Other

## (5) BORE HOLE CONSTRUCTION:

Special Construction approval Yes ☐ No ☒ Depth of Completed Well 30 ft.

Explosives used Yes ☐ No ☒ Type ____ Amount ____

| HOLE Diameter | From | To | SEAL Material | From | To | Amount sacks or pounds |
|---|---|---|---|---|---|---|
| 12 | 0 | 18 | Cement | 0 | 18 | 5 |
| 6 | 18 | 30 | | | | |

How was seal placed: Method ☐ A ☐ B ☐ C ☐ D ☐ E

☒ Other Tremie pipe

Backfill placed from ____ ft. to ____ ft. Material ____

Gravel placed from ____ ft. to ____ ft. Size of gravel ____

## (6) CASING/LINER:

| | Diameter | From | To | Gauge | Steel | Plastic | Welded | Threaded |
|---|---|---|---|---|---|---|---|---|
| Casing: | 6" | +1 | 30 | .250 | ☒ | ☐ | ☒ | ☐ |
| | | | | | ☐ | ☐ | ☐ | ☐ |
| | | | | | ☐ | ☐ | ☐ | ☐ |
| | | | | | ☐ | ☐ | ☐ | ☐ |
| Liner: | | | | | ☐ | ☐ | ☐ | ☐ |
| | | | | | ☐ | ☐ | ☐ | ☐ |

Final location of shoe(s) ____

## PERFORATIONS/SCREENS:

☒ Perforations Method Cutting torch

☐ Screens Type ____ Material ____

| From | To | Slot size | Number | Diameter | Tele/pipe size | Casing | Liner |
|---|---|---|---|---|---|---|---|
| 18 | 30 | 1/16 x 6 | 84 | 6" | ____ | ☒ | ☐ |
| | | | | | | ☐ | ☐ |
| | | | | | | ☐ | ☐ |
| | | | | | | ☐ | ☐ |
| | | | | | | ☐ | ☐ |
| | | | | | | ☐ | ☐ |

## (8) WELL TESTS: Minimum testing time is 1 hour

☐ Pump ☒ Bailer ☐ Air ☐ Flowing Artesian

| Yield gal/min | Drawdown | Drill stem at | Time |
|---|---|---|---|
| 40 | 8 ft. | | 1 hr. |
| | | | |
| | | | |

Temperature of water 56 Depth Artesian Flow Found NONE

Was a water analysis done? NO ☐ Yes By whom ____

Did any strata contain water not suitable for intended use? ☐ Too little

☐ Salty ☐ Muddy ☐ Odor ☐ Colored ☐ Other ____

Depth of strata: ____

## (9) LOCATION OF WELL by legal description:

County CROOK Latitude ____ Longitude ____

Township 15 N or S Range 16 E or W, WM.

Section 6 NE ¼ NE ¼

Tax Lot ____ Lot ____ Block ____ Subdivision ____

Street Address of Well (or nearest address) 220 West Third St. Prineville, Oregon 97754

## (10) STATIC WATER LEVEL:

5 ft. below land surface. Date 11-24-87

Artesian pressure NONE lb. per square inch. Date ____

## (11) WATER BEARING ZONES:

Depth at which water was first found 17 ft.

| From | To | Estimated Flow Rate | SWL |
|---|---|---|---|
| 17 | 25 | 50 | 5 |
| | | | |
| | | | |
| | | | |

## (12) WELL LOG:

Ground elevation ____

| Material | From | To | SWL |
|---|---|---|---|
| top soil | 0 | 5 | |
| Clay | 5 | 17 | |
| gravel (water bearing) | 17 | 30 | 5 |

Date started 11-24-87 Completed 11-24-87

**(unbonded) Water Well Constructor Certification:**

I certify that the work I performed on the construction, alteration, or abandonment of this well is in compliance with Oregon well construction standards. Materials used and information reported above are true to my best knowledge and belief.

WWC Number 4444

Signed ____ Date ____

**(bonded) Water Well Constructor Certification:**

I accept responsibility for the construction, alteration, or abandonment work performed on this well during the construction dates reported above. all work performed during this time is in compliance with Oregon well construction standards. This report is true to the best of my knowledge and belief.

WWC Number 4444

Signed Arch's Top Date 11-24-87

WHITE COPIES - WATER RESOURCES DEPARTMENT YELLOW COPY - CONSTRUCTOR PINK COPY - CUSTOMER 9809C 10/86