11

STATE OF OREGON WATER WELL REPORT

(as required by ORS 537.765)

Crook 3055

RECEIVED

AUG 12 1994

WATER RESOURCES DEPT.

155/16E/8ab

(START CARD) # 51593

Instructions for completing this report are on the last page of this form.

(1) OWNER: Well Number Rental

Name Bobby Kennedy

Address 2133 Crooked River Highway

City Prineville State Or Zip 97754

(2) TYPE OF WORK

[X] New Well [ ] Deepening [ ] Alteration (repair/recondition) [ ] Abandonment

(3) DRILL METHOD:

[X] Rotary Air [ ] Rotary Mud [ ] Cable [ ] Auger

[ ] Other

(4) PROPOSED USE:

[X] Domestic [ ] Community [ ] Industrial [ ] Irrigation

[ ] Thermal [ ] Injection [ ] Livestock [ ] Other

(5) BORE HOLE CONSTRUCTION:

Special Construction approval [ ] Yes [X] No Depth of Completed Well 39 ft.

Explosives used [ ] Yes [X] No Type Amount

HOLE Diameter	From	To	SEAL Material	From	To	Sacks or pounds
10"	0	20	Bentonite	0	20	20
8"	20	39				

How was seal placed: Method [ ] A [ ] B [ ] C [ ] D [ ] E

[X] Other Poured down dry

Backfill placed from ft. to ft. Material

Gravel placed from ft. to ft. Size of gravel

(6) CASING/LINER:

	Diameter	From	To	Gauge	Steel	Plastic	Welded	Threaded
Casing	6"	+2	4	.250	[X]	[ ]	[X]	[ ]
	5"	+1	38	CL126	[ ]	[X]	[ ]	[ ]
					[ ]	[ ]	[ ]	[ ]
					[ ]	[ ]	[ ]	[ ]
Liner:					[ ]	[ ]	[ ]	[ ]
					[ ]	[ ]	[ ]	[ ]

Final location of shoe(s)

(7) PERFORATIONS/SCREENS:

[X] Perforations Method Electric Saw

[ ] Screens Type Material

From	To	Slot size	Number	Diameter	Tele/pipe size	Casing	Liner
22	38	1/4	70			[X]	[ ]
						[ ]	[ ]
						[ ]	[ ]
						[ ]	[ ]
						[ ]	[ ]

(8) WELL TESTS: Minimum testing time is 1 hour

[ ] Pump [ ] Bailer [X] Air [ ] Flowing Artesian

Yield gal/min	Drawdown	Drill stem at	Time
55-60	8'	35	1 hr.

Temperature of water Depth Artesian Flow Found

Was a water analysis done? [ ] Yes By whom

Did any strata contain water not suitable for intended use? [X] Too little

[ ] Salty [ ] Muddy [X] Odor [ ] Colored [ ] Other

Depth of strata: 16-18'

(9) LOCATION OF WELL by legal description:

County Crook Latitude Longitude

Township 15S N or S Range 16E E or W. WM.

Section 8 NW 1/4 NE 1/4

Tax Lot 100 Lot Block Subdivision

Street Address of Well (or nearest address)

920 Fairgrounds Rd

(10) STATIC WATER LEVEL:

12 ft. below land surface. Date 1/19/94

Artesian pressure lb. per square inch. Date

(11) WATER BEARING ZONES:

Depth at which water was first found 16

From	To	Estimated Flow Rate	SWL
16	18	3-4-GPM	12
22	39	75-100	12

(12) WELL LOG:

Ground Elevation

Material	From	To	SWL
Sand & Gravel	0	2	
Clay & Strip of Gravel W/B	2	22	
Sand & Gravel W/B	22	39	12

Date started 1/18/94 Completed 1/19/94

(unbonded) Water Well Constructor Certification:

I certify that the work I performed on the construction, alteration, or abandonment of this well is in compliance with Oregon water supply well construction standards. Materials used and information reported above are true to the best of my knowledge and belief.

Signed Robert Bucher WWC Number 1385 Date 8-8-94

(bonded) Water Well Constructor Certification:

I accept responsibility for the construction, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon water supply well construction standards. This report is true to the best of my knowledge and belief.

Signed Robert Bucher WWC Number 1385 Date 8-8-94

ORIGINAL & FIRST COPY-WATER RESOURCES DEPARTMENT SECOND COPY-CONSTRUCTOR THIRD COPY-CUSTOMER