STATE OF OREGON

# WATER WELL REPORT

(as required by ORS 537.765)

CROO 450

14S/16E/33cd

(START CARD) # 46359

## (1) OWNER:

Well Number # 1

Name Mrs. Klapprich

Address 1955 Laughlin Rd.

City Prineville State Or. Zip 97754

## (2) TYPE OF WORK:

☐ New Well ☒ Deepen ☐ Recondition ☐ Abandon

## (3) DRILL METHOD:

☐ Rotary Air ☐ Rotary Mud ☒ Cable

☐ Other

## (4) PROPOSED USE:

☒ Domestic ☐ Community ☐ Industrial ☐ Irrigation

☐ Thermal ☐ Injection ☐ Other

## (5) BORE HOLE CONSTRUCTION:

Special Construction approval ☐ Yes ☒ No Depth of Completed Well 90 ft.

Explosives used ☐ Yes ☒ No Type Amount

| HOLE Diameter | From | To | SEAL Material | From | To | Amount sacks or pounds |
|---|---|---|---|---|---|---|
| 6" | 45 | 90 | | | | |

How was seal placed: Method ☐ A ☐ B ☐ C ☐ D ☐ E

☐ Other Existing

Backfill placed from ft. to ft. Material

Gravel placed from ft. to ft. Size of gravel

## (6) CASING/LINER:

| | Diameter | From | To | Gauge | Steel | Plastic | Welded | Threaded |
|---|---|---|---|---|---|---|---|---|
| Casing: | | | | | ☐ | ☐ | ☐ | ☐ |
| | | | | | ☐ | ☐ | ☐ | ☐ |
| | | | | | ☐ | ☐ | ☐ | ☐ |
| | | | | | ☐ | ☐ | ☐ | ☐ |
| Liner: | 5" | 0 | 80' | .188 | ☒ | ☐ | ☒ | ☐ |
| | | | | | ☐ | ☐ | ☐ | ☐ |

Final location of shoe(s)

## (7) PERFORATIONS/SCREENS:

☒ Perforations Method torch

☐ Screens Type Material

| From | To | Slot size | Number | Diameter | Tele/pipe size | Casing | Liner |
|---|---|---|---|---|---|---|---|
| 43 | 80 | 1/8 | 244 | 5" | | ☐ | ☒ |
| | | | | | | ☐ | ☐ |
| | | | | | | ☐ | ☐ |
| | | | | | | ☐ | ☐ |

## (8) WELL TESTS: Minimum testing time is 1 hour

☐ Pump ☒ Bailer ☐ Air ☐ Flowing Artesian

| Yield gal/min | Drawdown | Drill stem at | Time |
|---|---|---|---|
| 10 | -0- | | 1 hr. |
| | | | |
| | | | |
| | | | |

Temperature of Water 56 Depth Artesian Flow Found -0-

Was a water analysis done? ☐ Yes By whom

Did any strata contain water not suitable for intended use? ☐ Too little

☐ Salty ☐ Muddy ☐ Odor ☐ Colored ☐ Other

Depth of strata:

## (9) LOCATION OF WELL by legal description:

County Crook Latitude Longitude

Township 14S. N or S. Range 16E. E or W. WM.

Section 33 S.E. ¼ S.W. ¼

Tax Lot 300 Lot - Block Subdivision

Street Address of Well (or nearest address) 1955 Laughlin Prineville, Or. 97754

## (10) STATIC WATER LEVEL:

25' ft. below land surface. Date 8-10-92

Artesian pressure -0- lb. per square inch. Date

## (11) WATER BEARING ZONES:

Depth at which water was first found 25'

| From | To | Estimated Flow Rate | SWL |
|---|---|---|---|
| 25 | 65 | 10 | 25' |
| | | | |
| | | | |

## (12) WELL LOG:

Ground elevation

| Material | From | To | SWL |
|---|---|---|---|
| Fine Black sand | 45 | 65 | 25 |
| Sticky Black Clay | 65 | 90 | " |

RECEIVED
SEP - 9 1992
WATER RESOURCES DEPT.
SALEM, OREGON

Date started 8-10-92 Completed 8-12-92

**(unbonded) Water Well Constructor Certification:**

I certify that the work I performed on the construction, alteration, or abandonment of this well is in compliance with Oregon well construction standards. Materials used and information reported above are true to my best knowledge and belief.

Signed Earl Salisbury WWC Number 1382 Date 9-12-92

**(bonded) Water Well Constructor Certification:**

I accept responsibility for the construction, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon well construction standards. This report is true to the best of my knowledge and belief.

Signed Curt Clausen WWC Number 741 Date 8-12-92

ORIGINAL & FIRST COPY - WATER RESOURCES DEPARTMENT SECOND COPY - CONSTRUCTOR THIRD COPY - CUSTOMER 9809C 10/91