RECEIVED

FEB - 9 1998

WATER RESOURCES DEPT.
SALEM, OREGON

CROO 50476

WELL I.D.# L21971

(START CARD) # 94880

STATE OF OREGON
WATER SUPPLY WELL REPORT
(as required by ORS 537.765)

Instructions for completing this report are on the last page of this form.

(1) OWNER: Well Number

Name Sue Moore

Address Knight Ct.

City Prineville State OR Zip 97754

(2) TYPE OF WORK

[X] New Well [ ] Deepening [ ] Alteration (repair/recondition) [ ] Abandonment

(3) DRILL METHOD:

[ ] Rotary Air [ ] Rotary Mud [X] Cable [ ] Auger

[ ] Other

(4) PROPOSED USE:

[X] Domestic [ ] Community [ ] Industrial [ ] Irrigation

[ ] Thermal [ ] Injection [ ] Livestock [ ] Other

(5) BORE HOLE CONSTRUCTION:

Special Construction approval [ ] Yes [X] No Depth of Completed Well 29 ft.

Explosives used [ ] Yes [X] No Type Amount

HOLE Diameter	From	To	SEAL Material	From	To	Sacks or pounds
10"	0	18	BENTONITE	0	18	12 SACKS
6"	18	29				

How was seal placed: Method [ ] A [ ] B [ ] C [ ] D [ ] E

[X] Other Hand Plug + Bentonite Poured Dry

Backfill placed from ft. to ft. Material

Gravel placed from ft. to ft. Size of gravel

(6) CASING/LINER:

	Diameter	From	To	Gauge	Steel	Plastic	Welded	Threaded
Casing:	6"	+1	30	250	[X]	[ ]	[X]	[ ]
					[ ]	[ ]	[ ]	[ ]
					[ ]	[ ]	[ ]	[ ]
					[ ]	[ ]	[ ]	[ ]
Liner:					[ ]	[ ]	[ ]	[ ]
					[ ]	[ ]	[ ]	[ ]

Final location of shoe(s) 29'

(7) PERFORATIONS/SCREENS:

[X] Perforations Method TORCH CUT

[ ] Screens Type Material

From	To	Slot size	Number	Diameter	Tele/pipe size	Casing	Liner
18	25	1/16 x 6	100	1/16 x 6	6" 250	[X]	[ ]
						[ ]	[ ]
						[ ]	[ ]
						[ ]	[ ]
						[ ]	[ ]

(8) WELL TESTS: Minimum testing time is 1 hour

[ ] Pump [X] Bailer [ ] Air [ ] Flowing Artesian

Yield gal/min	Drawdown	Drill stem at	Time
30+	0	BAILED	1 hr.

Temperature of water 58° Depth Artesian Flow Found

Was a water analysis done? [ ] Yes By whom

Did any strata contain water not suitable for intended use? [ ] Too little

[ ] Salty [ ] Muddy [ ] Odor [ ] Colored [ ] Other

Depth of strata:

(9) LOCATION OF WELL by legal description:

County CROOK Latitude Longitude

Township 15 N or [X] S Range 16 [X] E or W. WM.

Section 5 NW 1/4 NE 1/4

Tax Lot 5600 Lot Block Subdivision

Street Address of Well (or nearest address) Knight Ct. Prineville OR

(10) STATIC WATER LEVEL:

3 ft. below land surface. Date 12/26/97

Artesian pressure 0 lb. per square inch. Date 12/26/97

(11) WATER BEARING ZONES:

Depth at which water was first found 18'

From	To	Estimated Flow Rate	SWL
18'	26'	30+ gpm	3

(12) WELL LOG:

Ground Elevation

Material	From	To	SWL
Top Soil Loam	0	6'	
Clay Clay	6'	12	
Clay Clay + Gravels	12	24	
Broken Sand	24	26	3
Clay Sandy Clay	26	29	

Date started 12/24/97 Completed 12/24/97

(unbonded) Water Well Constructor Certification:

I certify that the work I performed on the construction, alteration, or abandonment of this well is in compliance with Oregon water supply well construction standards. Materials used and information reported above are true to the best of my knowledge and belief.

WWC Number

Signed Date

(bonded) Water Well Constructor Certification:

I accept responsibility for the construction, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon water supply well construction standards. This report is true to the best of my knowledge and belief.

WWC Number 1355

Signed [signature] Date 12/26/97

ORIGINAL & FIRST COPY-WATER RESOURCES DEPARTMENT SECOND COPY-CONSTRUCTOR THIRD COPY-CUSTOMER